

### **APPRAISAL**

www.vabfleetservices.be Date: 11/04/2017 1/5

ASK8KF

[X] EFFECTIVE [ ] NOT EXECUTED [X] COLLECTION [ ] DELIVERY

[x] = Status Modification

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 172668 KM File nr. : Mileage start / arrival: 0 / 01387122 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1EEF471 / WBA1C91020J504474 / E-File nr. : First registration: 06/11/2012 Color: VFS-nr.: **BLACK** Make + Model : Fuel type : BMW / 1 HATCH **DIESEL** Object nr. : Fuel: 40285 Classification: **Environment Class:** EURO 5 Customer company: Co2: YOUNG&RUBICAM GROUP NV 99g/kmDriver : Remote controls: 2 TISSUE Covering: Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): 0 Vehicle type: 1 HATCH 116d Eff.Dyn.Ed. 116PK Country registration: **BELGIUM** 

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:		1	



## **APPRAISAL**

Date: 11/04/2017 www.vabfleetservices.be 2/5

Original registr. number :	OK		Service manual :		
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :		[x]	Filled up :	0	

### Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre:	OK	[	[x] 1	.6-2 /	Rim:	[x]	/	Hubcap: [2	s SCRATCHED
Wheel RL:	[x]	MICHELIN	Tyre:	OK	[	[x] 1	.6-2 /	Rim:		/	Hubcap:	
Wheel FR:	[x]	MICHELIN	Tyre:	x] OK	[	[x] 1	.6-2 /	Rim:		/	Hubcap: [2	s] SCRATCHED
Wheel RR:	[x]	MICHELIN	Tyre:	OK	[	[x] 1	.6-2 /	Rim:		/	Hubcap:	
Wheel RES:	[x]		Tyre:	OK		/	/	Rim:		/	Hubcap:	
		[x]	Width			Heig	ght		Type		Rim	Index
Fron	t tyre		205			55	5		R		16	W

_	[]		8	- J P -		
	Front tyre	205	55	R	16	W
	Rear tyre	205	55	R	16	W

Remark:

### Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:
_					

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



HUB CAP FR

3 0 LU =0.00 EUR

## **APPRAISAL**

11/04/2017 Date: www.vabfleetservices.be 3/5

STATUS: ACCEPTABLE / USAGE DAMAGE									
Во	dywork \& windows								
[x]	REAR MUDGUARD/RIGHT/CENTER		SCRATCH (WITHOUT PAINT DAMAGE)	POLIEREN OVB					
[x]	REAR DOOR/LEFT/CENTER		SCRATCH (WITHOUT PAINT DAMAGE)						
x]	ROOF/REAR/RIGHT		SCRATCH (WITHOUT PAINT DAMAGE)						
x]	REAR DOOR/RIGHT/CENTER		SCRATCH (WITHOUT PAINT DAMAGE)	POLIEREN OVB					
<b>K</b> ]	FRONT DOOR/LEFT/CENTER		SCRATCH WITH PAINT DAMAGE						
x]	FRONT DOOR/RIGHT/CENTER		SCRATCH (WITHOUT PAINT DAMAGE)	POLIEREN OVB					
x]	FRONT MUDGUARD/RIGHT/CENTER		SCRATCH (WITHOUT PAINT DAMAGE)	POLIEREN OVB					
ът	ATUS. NOT ACCEPTAG	. –							
וכ	ATUS: NOT ACCEPTAE	BLE							
	dywork \& windows	SLE							
30		SLE	SCRATCH WITH PAINT DAMAGE						
ВО	dywork \& windows	Repair paint - LI	SCRATCH WITH PAINT DAMAGE  New paint - E	Depr.	Total				
30	dywork \& windows			<b>Depr.</b> 50 %	Total 254.16 EUR				
<b>30</b>	dywork \& windows  REAR BUMPER/LEFT/CORNER	Repair paint - LI							
<b>30</b>	dywork \& windows  REAR BUMPER/LEFT/CORNER  2 0 LU =0.00 EUR	Repair paint - LI	New paint - E						
<b>30</b>	dywork \& windows  REAR BUMPER/LEFT/CORNER  2 0 LU =0.00 EUR  REAR MUDGUARD/LEFT/REAR	Repair paint - LI 254.16 EUR	New paint - E  SCRATCH WITH PAINT DAMAGE	50 %	254.16 EUR				
<b>30</b>	dywork \& windows  REAR BUMPER/LEFT/CORNER  2 0 LU =0.00 EUR  REAR MUDGUARD/LEFT/REAR  Number Code	Repair paint - LI 254.16 EUR  Description	New paint - E  SCRATCH WITH PAINT DAMAGE  Unit price	50 % <b>Depr.</b>	254.16 EUR Total				
<b>30</b> (x)	dywork \& windows  REAR BUMPER/LEFT/CORNER  2 0 LU =0.00 EUR  REAR MUDGUARD/LEFT/REAR  Number Code  2 I 1 i-vab-sp-01	Repair paint - LI 254.16 EUR  Description	New paint - E  SCRATCH WITH PAINT DAMAGE  Unit price  115.56 EUR	50 % <b>Depr.</b>	254.16 EUR Total				
<b>30</b> (x)	dywork \& windows  REAR BUMPER/LEFT/CORNER  2 0 LU =0.00 EUR  REAR MUDGUARD/LEFT/REAR  Number Code  2 I 1 i-vab-sp-01	Repair paint - LI 254.16 EUR  Description  SPOTREPAIR	New paint - E  SCRATCH WITH PAINT DAMAGE  Unit price  115.56 EUR  SCRATCH WITH PAINT DAMAGE	50 %  Depr.  50 %	254.16 EUR  Total  115.56 EUR				
30 x] x]	REAR BUMPER/LEFT/CORNER  2 0 LU =0.00 EUR  REAR MUDGUARD/LEFT/REAR  Number Code  2 I 1 i-vab-sp-01  FRONT BUMPER/LEFT/SIDE	Repair paint - LI 254.16 EUR  Description  SPOTREPAIR  Repair paint - LI	New paint - E  SCRATCH WITH PAINT DAMAGE  Unit price  115.56 EUR  SCRATCH WITH PAINT DAMAGE	50 %  Depr.  50 %  Depr.	254.16 EUR  Total  115.56 EUR  Total				
30 x] x]	REAR BUMPER/LEFT/CORNER  2 0 LU =0.00 EUR  REAR MUDGUARD/LEFT/REAR  Number Code  2 I 1 i-vab-sp-01  FRONT BUMPER/LEFT/SIDE  1 0 LU =0.00 EUR	Repair paint - LI 254.16 EUR  Description  SPOTREPAIR  Repair paint - LI	New paint - E  SCRATCH WITH PAINT DAMAGE  Unit price  115.56 EUR  SCRATCH WITH PAINT DAMAGE	50 %  Depr.  50 %  Depr.	254.16 EUR  Total  115.56 EUR  Total				

New paint - E

Repair paint - LI

Total

Depr.

50 %



127.08

184.86

36.00

0

## **APPRAISAL**

Date: 11/04/2017 www.vabfleetservices.be 4/5

eces										
Numb	er (	Code		Description			Unit pri	ice Depr.		Total
3 1	,	WHEEL CAP					36.00 E	UR 50 %		36.00 EUR
Numb	oer (	Code		Description			Unit pri	ice Depr.		Total
3 1	,	WHEEL CAP					36.00 E	UR 50 %		36.00 EUF
1	ĺ	2	3	4	5	6	7	8	9	10
254.16	T	369.72	72.00	0	0	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
695.88		0	580.32	115.56
347.94	NA Deprec.		BG: 2	HOG: 0
	0.00%			
245.04	TOTAL			

0

0

0

0

TOTAL 347.94

0

0



# **APPRAISAL**

www.vabfleetservices.be Date: 11/04/2017 5/5

[x] = Status Modification

Pictures: No

CIRCUMS'	TANCES		UNDER CONDITION - DUSTY VEHICLE					
Extra Time :	0 min	Waiting time: 0 m Reason:	nin	Towing time : Reason :	0 min			
NOT EXECUTED :	No	<u> </u>						
Remark :	'							
Prices in EUR v	vithout VAT							
Authorized by customer :			Executed by VAB	Fleet Services				
Remark authorized	customer :							
Date :	11/04/2017	<b>Hour:</b> 09:30						
Company:  Executed by VAB For Services	leet							
E-Mail:	@							
Signature authorized	by customer		+					
	L							