

ARO4KE

☒ EFFECTIVE ☐ NOT EXECUTED ☐ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	182205 KM
File nr. :	1386469	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
BH7330 / VF38E9HD8EL015455 /		yr of constructionr :	/
E-File nr. :		First registration :	05/05/2014
VFS-nr. :		Color :	BLACK
Make + Model :	PEUGEOT / 508 BREAK	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :	A	Environment Class:	
Customer company :	ONBEKEND	Co2:	g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	LUXEMBOURG

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	114	kW:	84
Fisc HP		Imported vehicle:	Yes
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	Service manual :
Cert. of reg. / Part 1:	Cert. of conformity :
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest : OK [x]	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit :	Warning triangle : OK [x]
Jack, wheelspanner : OK [x]	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Winter tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	1.6-2 /	Rim :	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	1.6-2 /	Rim :	/ Hubcap : [x] MISSING/INCOMPLETE
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	1.6-2 /	Rim :	/	Hubcap :
Wheel RES:	[x]	MICHELIN	Tyre :	OK	[x]	>6 /	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	60	R	16	WINTER H
Rear tyre	215	60	R	16	WINTER H

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/CENTER/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	BONNET/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE	POLIJSTEN OVB.

Interior

[x]	DOOR IN FL	SCRATCHED
[x]	BOOT LID IN	SCRATCHED

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	MEERDERE	
		Repair paint - LI	New paint - E	Depr.
5	0 LU =0.00 EUR	211.80 EUR		50 %
				211.80 EUR
[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.
4	0 LU =0.00 EUR	318.35 EUR		50 %
				318.35 EUR
[x]	FRONT DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	+DEUKEN	
		Repair paint - LI	New paint - E	Depr.
3	0 LU =0.00 EUR	318.35 EUR		50 %
				318.35 EUR
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.
6	0 LU =0.00 EUR	318.35 EUR		50 %
				318.35 EUR
[x]	FRONT MUDGUARD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.
7	0 LU =0.00 EUR	220.18 EUR		50 %
				220.18 EUR

[x]	FRONT BUMPER/RIGHT/SIDE	SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.
				Total
2	0 LU =0.00 EUR	211.80 EUR		50 %
				211.80 EUR

Interior

[x]	DASHBORD	OTHER DAMAGES		
		Repair paint - LI	New paint - E	Depr.
				Total
1	10 LU =48.00 EUR	0 EUR		50 %
				48.00 EUR

[x]	CENTER CONSOLE	MISSING/INCOMPLETE		
		Repair paint - LI	New paint - E	Depr.
				Total
1	0 LU =0.00 EUR	0 EUR		50 %

[x]	CARPET FL	HOLE		
		Repair paint - LI	New paint - E	Depr.
				Total
1	40 LU =192.00 EUR	0 EUR		
				192.00 EUR

[x]	SEAT FR	HOLE		
		Repair paint - LI	New paint - E	Depr.
				Total
1	25 LU =120.00 EUR	0 EUR		50 %
				120.00 EUR

[x]	ROOF UPHOLSTERY	HOLE		
	Number Code	Description	Unit price	Depr.
				Total
1	I 1 i-vab-intvlr-01	VELOURS REPAIR (MAX 3CM LENGTH OR DIAMATER)	64.32 EUR	
				64.32 EUR

[x]	FLOOR BOOT	SCRATCHED		
	Number Code	Description	Unit price	Depr.
				Total
0	0			

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE	SCRATCH WITH PAINT DAMAGE		
	Number Code	Description	Unit price	Depr.
				Total
9	I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR	
				115.56 EUR

Others

	HUB CAP FR			
		Repair paint - LI	New paint - E	Depr.
				Total
8	0 LU =0.00 EUR			50 %

Pieces					
Number	Code	Description	Unit price	Depr.	Total
1	1	BEKERHOUDER	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
1	1	ASBAK	10.00 EUR	50 %	10.00 EUR
Number	Code	Description	Unit price	Depr.	Total
1	1	CARPET	60.00 EUR		60.00 EUR
Number	Code	Description	Unit price	Depr.	Total
8	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
1	1	CARPET	60.00 EUR	50 %	60.00 EUR

1	2	3	4	5	6	7	8	9	10
584.32	211.80	318.35	318.35	211.80	318.35	220.18	30.00	115.56	0
450.32	105.90	159.18	159.18	105.90	159.18	110.09	15.00	115.56	0

INNOVATIVE	TRADITIONAL	GENERAL	
179.88	2148.83	0	2328.71
HOG: 0	BG: 0		NA Deprec. 1380.30
			0.00%
			TOTAL 1380.30

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : ACHTERKANT ZETELS L EN R VOOR KRASSEN [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 06/04/2017 Hour : 14:23 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	