

ARWLJ8

☒ EFFECTIVE    ☐ NOT EXECUTED    ☒ COLLECTION    ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	186340 KM
File nr. :	1386644	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1CXV797 / YV1DZ87A4C2320592 /		yr of constructionr :	2012 / 00
E-File nr. :		First registration :	22/03/2012
VFS-nr. :		Color :	GOLD
Make + Model :	VOLVO / XC60	Fuel type :	DIESEL
Object nr. :	52258	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	BALOISE BELGIUM NV	Co2:	149g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	SUV	Engine size:	2400
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	163	kW:	120
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
		Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK
Jack, wheelspanner :		Filled up :	0	

## Wheels and tyres: Winter tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6 /	Rim :			/	Hubcap :	
Wheel FR :	[x]	BRIDGESTONE	Tyre :	[x]	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	235	60	R	18	M+S
Rear tyre	235	60	R	18	M+S

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE		
[x]	REAR WINDOW STYLE/RIGHT/FRONT	DENT	+KRAS MET LAKSCHADE	
[x]	FRONT DOOR/LEFT/FRONT	DENT		
[x]	REAR DOOR/LEFT/LEFT	SCRATCH WITH PAINT DAMAGE		

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	WINDSCREEN/RIGHT		WINDOW DAMAGE			
	Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-herstr-01	WINDOW REPAIR	58.80 EUR		58.80 EUR
[x]	BONNET/CENTER/LEFT		DENT			
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	FRONT BUMPER/RIGHT		SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.	Total
1	20 LU =96.00 EUR		211.80 EUR		50 %	307.80 EUR

### Accessories and others

[x]	DOORHANDLE	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	150.00 EUR		50 %	150.00 EUR

1	2	3	4	5	6	7	8	9	10
307.80	63.00	150.00	58.80	0	0	0	0	0	0
153.90	63.00	75.00	58.80	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
121.80	457.80	0	579.60
HOG: 0	BG: 0		NA Deprec. 350.70
			0.00%
			TOTAL 350.70



[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

## Prices in EUR without VAT

Authorized by customer :  Remark authorized customer :  Date : 10/04/2017      Hour : 11:45 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	