

ARXUDN

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	167324 KM
File nr. :	1386667	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1BRY479 / VF1FLBMB6BY405229 /		yr of constructionr :	/
E-File nr. :		First registration :	18/08/2011
VFS-nr. :		Color :	WHITE
Make + Model :	RENAULT / TRAFIC	Fuel type :	DIESEL
Object nr. :	72331	Fuel :	
Classification :		Environment Class:	EURO 4
Customer company :	MULDERS COOLTECH	Co2:	195g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :	TRAFIC 29 B/F MWB L2H1 Gr.Conf.90PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BESTELWAGEN	Engine size:	1995
Gear box :	Manueel	Number of places:	3
Number of gears:	5	Number of doors:	5
HP:	90	kW:	66
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:	
--------------------	--

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
			Warning triangle :	OK [x]
First aid kit :	OK	[x]	Oil level :	OK [x]
Jack, wheelspanner :			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	>6 /	Rim :	/	Hubcap :	[x]	MISSING/INCOMPLETE	
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	>6 /	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	205	65	R	16	
Rear tyre	205	65	R	16	

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE			
	Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR
[x]	REAR MUDGUARD/LEFT/FRONT		SCRATCH WITH PAINT DAMAGE		+DEUK	
			Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR		231.15 EUR		50 %	231.15 EUR
[x]	REAR DOOR/RIGHT/CENTER		DENT		2X	
	Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
	Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-uitd-02	BEAT OUT DENT SUPPL	19.80 EUR		19.80 EUR
[x]	WINDSCREEN/CENTER/RIGHT		SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.	Total
6	0 LU =0.00 EUR		0 EUR		50 %	
			Repair paint - LI	New paint - E	Depr.	Total
6	25 LU =120.00 EUR		0 EUR		50 %	120.00 EUR
[x]	FRONT DOOR/RIGHT/CENTER		DENT			
			Repair paint - LI	New paint - E	Depr.	Total
5	0 LU =0.00 EUR		238.76 EUR		50 %	238.76 EUR
[x]	REAR DOOR/LEFT/LEFT		DENT		+ANDERE SCHADE, ROEST	
			Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR		226.26 EUR		50 %	226.26 EUR

Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE		BROKEN / CRACKED			
			Repair paint - LI	New paint - E	Depr.	Total
8	0 LU =0.00 EUR		0 EUR		50 %	
			Repair paint - LI	New paint - E	Depr.	Total
8	10 LU =48.00 EUR		0 EUR		50 %	48.00 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
7	I 3	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	43.74 EUR

HUB CAP FL

	Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR		50 %	

HUB CAP REAR L

	Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR		50 %	

HUB CAP REAR RIGHT

	Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR		50 %	

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR		50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR

Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR

Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR

Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR

Number	Code	Description	Unit price	Depr.	Total
2	1	SIDE PROTECTION	10.80 EUR	50 %	10.80 EUR

Number	Code	Description	Unit price	Depr.	Total
6	1	WIND SCREEN	275.40 EUR	50 %	275.40 EUR

Number	Code	Description	Unit price	Depr.	Total
8	1	MIRROR	90.00 EUR	50 %	90.00 EUR

1	2	3	4	5	6	7	8	9	10
90.00	241.95	226.26	193.44	238.76	395.40	43.74	138.00	0	0
45.00	120.98	113.13	193.44	119.38	197.70	43.74	69.00	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
237.18	1330.37	0	1567.55
HOG: 0	BG: 3		NA Deprec. 902.36
			0.00%
			TOTAL 902.36

APPRAISAL

www.vabfleetservices.be

Date : 06/04/2017

6/6

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min 	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 06/04/2017 Hour : 08:38	
Company :	
Executed by VAB Fleet Services	
E-Mail : @	
Signature authorized by customer	
	