

AR67FV

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------|-------------------------|--------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 138370 KM |
| File nr. : | 1386095 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1DBL674 / YV1BW84A1C1242801 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 02/04/2012 |
| VFS-nr. : | | Color : | BEIGE |
| Make + Model : | VOLVO / V70 | Fuel type : | DIESEL |
| Object nr. : | 12144 | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | SYRAL BELGIUM NV | Co2: | 119g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | LEATHER | Number keys : | 2 [x] |
| Vehicle kind : | | Seats (minivan) : | 0 |
| Vehicle type : | V70 DRIVe Kinetic 115PK | Country registration : | BELGIUM |

| | | | |
|------------------------------|---------|---------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | Yes |
| Variant car: | BREAK | Engine size: | 1560 |
| Gear box : | Manueel | Number of places: | 5 |
| Number of gears: | 6 | Number of doors: | 5 |
| HP: | 114 | kW: | 84 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | No | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |

| |
|--------------------|
| General condition: |
|--------------------|

| | | | | |
|------------------------------|----|-----------------------|-------------------------|--------|
| Original registr. number : | OK | Service manual : | OK | [x] |
| Cert. of reg. / Part 1: | | Cert. of conformity : | OK | |
| Cert. of reg. copy / Part 2: | OK | [x] | Insurance certificate : | |
| Warning vest : | OK | [x] | Transport licence : | |
| Tax certificate : | | | Navigation CD/SD/DVD | |
| Fuel card : | | | Car radio : | OK [x] |
| Mobile phone kit : | | | Extinguisher : | OK [x] |
| | | | Warning triangle : | OK [x] |
| First aid kit : | OK | [x] | Oil level : | OK [x] |
| Jack, wheelspanner : | OK | [x] | Filled up : | 0 |

Wheels and tyres: Winter tires

| | | | | | | | | | | | | |
|------------|------------|----------|--------|-----|--------|-------|-------|-------|-----------------|-----------------|----------|----------|
| Wheel FL: | [x] | FULDA | Tyre : | OK | [x] | 2-4 / | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : | |
| Wheel RL : | [x] | GOODYEAR | Tyre : | OK | [x] | 2-4 / | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : | |
| Wheel FR : | [x] | FULDA | Tyre : | [x] | OK | [x] | 2-4 / | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : |
| Wheel RR : | [x] | GOODYEAR | Tyre : | OK | [x] | 2-4 / | Rim : | | | / | Hubcap : | |
| Wheel RES: | [x] | ANDERE | Tyre : | OK | | / | Rim : | | | / | Hubcap : | |
| | | | | | | | | | | | | |
| | [x] | | Width | | Height | | Type | | Rim | | Index | |
| | Front tyre | | 205 | | 60 | | R | | 16 | | WINTER H | |
| | Rear tyre | | 205 | | 60 | | R | | 16 | | WINTER H | |
| | | | | | | | | | | | | |
| Remark : | | | | | | | | | | | | |

Remark :

Wheels and tyres:

| | | | | | | |
|------------|--------|-------|--------|-------|-----|----------|
| Wheel FL: | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: | Tyre : | OK | / | Rim : | / | Hubcap : |
| | | | | | | |
| | [x] | Width | Height | Type | Rim | Index |
| Front tyre | | 0 | 0 | R | 0 | |
| Rear tyre | | 0 | 0 | R | 0 | |

Remark :

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

| | | | |
|-----|-----------------------------|--------------------------------|------------------------------|
| [x] | REAR MUDGUARD/LEFT/CENTER | SCRATCH (WITHOUT PAINT DAMAGE) | |
| [x] | REAR MUDGUARD/RIGHT/FRONT | SCRATCH (WITHOUT PAINT DAMAGE) | |
| [x] | FRONT DOOR/RIGHT/CENTER | SCRATCH (WITHOUT PAINT DAMAGE) | MEERDERE |
| [x] | BONNET/CENTER/RIGHT | SCRATCH (WITHOUT PAINT DAMAGE) | POLIEREN OVB MEERDERE + DUEK |
| [x] | FRONT MUDGUARD/RIGHT/CENTER | SCRATCH (WITHOUT PAINT DAMAGE) | MEERDERE |

Accessories and others

| | | |
|-----|-------------------------------|--------------------------------|
| [x] | OUTSIDE MIRROR RIGHTHAND SIDE | SCRATCH (WITHOUT PAINT DAMAGE) |
|-----|-------------------------------|--------------------------------|

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| | | | | |
|-----|-------------------------|---------------------------|---------------|------------|
| [x] | REAR BUMPER/CENTER/LEFT | SCRATCH WITH PAINT DAMAGE | +DEUKEN | |
| | | Repair paint - LI | New paint - E | Depr. |
| | | | | Total |
| 2 | 0 LU =0.00 EUR | 254.16 EUR | | 50 % |
| | | | | 254.16 EUR |
| [x] | REAR DOOR/RIGHT/FRONT | SCRATCH WITH PAINT DAMAGE | MEERDERE | |
| | | Repair paint - LI | New paint - E | Depr. |
| | | | | Total |
| 3 | 0 LU =0.00 EUR | 382.02 EUR | | 50 % |
| | | | | 382.02 EUR |
| [x] | FRONT BUMPER/RIGHT/SIDE | SCRATCH WITH PAINT DAMAGE | +LINKS | |
| | | Repair paint - LI | New paint - E | Depr. |
| | | | | Total |
| 1 | 0 LU =0.00 EUR | 254.16 EUR | | 50 % |
| | | | | 254.16 EUR |

Interior

| | | | | |
|-----|---------|-----------|-------------|------------|
| [x] | SEAT FL | SCRATCHED | | |
| | | | | |
| | Number | Code | Description | Unit price |
| | | | | Depr. |
| | | | | Total |
| 0 | 0 | | | |

Others

| | | | | | |
|---|--------|-------------------|--------------------|------------|-----------|
| | | | RIM FRONT LEFT | | |
| | | | | | |
| | Number | Code | Description | Unit price | Depr. |
| | | | | | Total |
| 4 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | 95.00 EUR |

RIM REAR LEFT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------------|--------------------|-----------|-----------|
| 4 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | 95.00 EUR |

RIM FRONT RIGHT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------------|--------------------|-----------|-----------|
| 4 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | 95.00 EUR |

Pieces

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------------------|------------|-------|------------|
| 3 | 1 | SIDE PROTECTION PAINTED | 120.00 EUR | 50 % | 120.00 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|--------|--------|--------|---|---|---|---|---|----|
| 254.16 | 254.16 | 502.02 | 285.00 | 0 | 0 | 0 | 0 | 0 | 0 |
| 127.08 | 127.08 | 251.01 | 285.00 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|-------------------|
| 285.00 | 1010.34 | 0 | 1295.34 |
| HOG: 0 | BG: 2 | | NA Deprec. 790.17 |
| | | | 0.00% |
| | | | TOTAL 790.17 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

| | | |
|-------------------------------|----------------------------------|---------------------------------|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|--|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 10/04/2017 Hour : 15:24 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |