

www.vabfleetservices.be Date: 10/07/2017 1/4

BVBYD6

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

Commissionar: **KBC REMARKETING** Cleanliness: INT: CLEAN [x] EXT: DIRTY [x] Owner: Mileage : 63455 KM File nr. : Mileage start / arrival: 0 / 01417227 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1HTP649 / WBA1C91070P872730 / E-File nr. : First registration: 30/09/2014 VFS-nr.: Color: **BLACK** Make + Model : Fuel type : BMW / 1 HATCH **DIESEL** Object nr. : Fuel: 4067 **Environment Class:** Classification: EURO 5 Customer company: Co2: **ERNST & YOUNG** 99g/kmBEDRIJFSREVISOREN CVBA Driver: Remote controls: 2 Number keys : Covering: TISSUE 2[x]Vehicle kind: VEHICLE Seats (minivan): Vehicle type: Country registration: **BELGIUM**

		•					
Variant car:		Engine size:	1598				
Gear box :	Manueel	Number of places:	5				
Number of gears:	6	Number of doors:	5				
нр:	116	kW:	85				
Fisc HP		Imported vehicle:	No				
Animals transported:	No	Smoked in vehicle:	No				
Due date vehicle inspection:		Extra set of tires:	No				
		Use:	Unknown				
General condition:	General condition:						

Metallic paint:

Yes



www.vabfleetservices.be Date: 10/07/2017 2/4

Original registr. number :	OK		Service manual :		
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres: Winter tires

F	Rear tyre		205			5	55	Ī	R		16	Н
F	ront tyre		205			5	55		R		16	Н
		[x]	Width			Hei	ight		Туре		Rim	Index
Wheel RE	S: [x]		Tyre:		OK	[x]	/	Rim:		/	Hubcap :	
Wheel RR	: [x]	DUN	LOP Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel FR	: [x]	DUN	LOP Tyre:	[x]	OK	[x]	4-6 /	Rim:		/	Hubcap:	
Wheel RL	: [x]	DUN	LOP Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel FL:	[x]	DUN	LOP Tyre:		OK	[x]	4-6 /	Rim:		/	Hubcap:	

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

	[x]	Width	Height	Type	Rim	Index
Fron	ıt tyre	0	0	R	0	
Rear	r tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 10/07/2017 3/4

STATUS: NOT ACCEPTABLE

Во	dywork \	& window	s								
[x]	REAR DO	OR/RIGHT/FRON	NT			DENT					
	Number	Code		Description	Description			Unit price Depr.			
	2 I 1	i-vab-uitd-01		BEAT OUT	DENT		63.00 EU	TR .		63.00 EUR	
[x]	BONNET/	CENTER/RIGHT	FRONT		SCRATCH WITH PAINT DAMAGE						
				Repair pain	Repair paint - LI New paint - E			Depr.			
	1 0 LU =0.00) EUR		348.09 EUR	348.09 EUR			50 %			
	1	2	3	4	5	6	7	8	9	10	
	348.09	63.00	0	0	0	0	0	0	0	0	
	174.04	63.00	0	0	0	0	0	0	0	0	
_	INNOV	ATIVE	TRADI	TIONAL GENERAL							
F	63.	63.00 34		18.09		0				411.09	
	НОС	G: 0	В	G: 2			NA Depr	ec.		237.04	
_					-		0.00%	1			

TOTAL

237.04



www.vabfleetservices.be Date: 10/07/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUM	ISTANCES		NORMAL CONCLUSION						
Extra Time :	0 min	Waiting time: 0 min Reason:	1	Towing time: 0 min Reason:					
NOT EXECUTE Reason :	ED: No								
Remark :									
Prices in EUI	R without VAT								
Authorized by customer :			Executed by VAB Flee	et Services					
Remark authoriz	zed customer :								
Date :	10/07/2017	Hour: 08:16							
Company : Executed by VAI Services	B Fleet								
E-Mail:	@								
Signature authoriz	zed by customer		 						