

www.vabfleetservices.be Date: 06/07/2017 1/4

BUSO4G

## [X] EFFECTIVE [ ] NOT EXECUTED [X] COLLECTION [ ] DELIVERY

[x] = Status Modification

VAT over the margin - car:

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	92058 KM
File nr. :	1416824	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HLU704 / WBA1C91080P69	5038 /	yr of constructionr:	/
E-File nr. :		First registration :	22/08/2014
VFS-nr. :		Color :	GREY
Make + Model :	BMW / 1 HATCH	Fuel type :	DIESEL
Object nr. :	4067	Fuel:	
Classification:		Environment Class:	EURO 5
Customer company :	ERNST & YOUNG BEDRIJFSREVISOREN	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Metallic paint:

Yes



Insurance certificate:

www.vabfleetservices.be Date: 06/07/2017 2/4

Original registr. number: OK Service manual:

Cert. of reg. / Part 1: OK [x] Cert. of conformity: OK

Cert. of reg. copy / Part 2:

Warning vest: OK [x] Transport licence:

Tax certificate : Navigation CD/SD/DVD

Fuel card: Car radio: OK [x]

Mobile phone kit: Extinguisher: OK [x]

Warning triangle: OK [x]

0

First aid kit: NOK [x] Oil level: OK [x]

Jack, wheelspanner: Filled up:

#### Wheels and tyres: Summer tires

Wheel FL: [x] MICHELIN Tyre: OK [x] 4-6/ Rim: / Hubcap: [x] SCRATCHED

Wheel RL: [x] MICHELIN Tyre: OK [x] 2-4/ Rim: / Hubcap:

Wheel FR: [x] MICHELIN Tyre: [x] OK [x] 4-6/ Rim: / Hubcap: [x] SCRATCHED

Wheel RR: [x] MICHELIN Tyre: OK [x] 2-4/ Rim: / Hubcap:

Wheel RES: [x] Tyre: OK / Rim: / Hubcap:

[x] Width		Height	Туре	Rim	Index
Front tyre	205	55	R	16	W
Rear tyre	205	55	R	16	W

Remark:

### Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim:	/	Hubcap :
Wheel RL:	Tyre:	OK	/	Rim:	/	Hubcap:

 Wheel FR:
 Tyre:
 OK
 / Rim:
 / Hubcap:

 Wheel RR:
 Tyre:
 OK
 / Rim:
 / Hubcap:

Wheel RES:

Tyre:

OK / Rim:

/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



06/07/2017 www.vabfleetservices.be Date: 3/4

#### STATUS: ACCEPTABLE / USAGE DAMAGE Bodywork \& windows [x] REAR BUMPER/CENTER/LEFT WINDOW DAMAGE ROOF/CENTER/RIGHT DENT [x] ROOF/CENTER/LEFT DENT [x] STATUS: NOT ACCEPTABLE **Others** HUB CAP FL Repair paint - LI New paint - E Depr. Total 1 0 LU =0.00 EUR 50 % HUB CAP FR Repair paint - LI New paint - E Total Depr. 1 0 LU =0.00 EUR 50 %

Piec	es					
	Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP		36.00 EUR	50 %	36.00 EUR
	Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP		36.00 EUR	50 %	36.00 EUR

1	2	3	4	5	6	7	8	9	10
72.00	0	0	0	0	0	0	0	0	0
36.00	0	0	0	0	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
72.00		0	72.00	0
36.00	NA Deprec.		BG: 2	HOG: 0
	0.00%			
36.00	TOTAL			



www.vabfleetservices.be Date: 06/07/2017 4/4

[x] = Status Modification

**Pictures:** No

CIRCUMS			NORMAL CO	ONCLUSION	
Extra Time :	0 min	Waiting time: 0 n Reason:	nin	Towing time : Reason :	0 min
NOT EXECUTED Reason:	: No				
Remark:					
Prices in EUR	without VAT				
Authorized by customer :			Executed by VAB I	Fleet Services	
Remark authorized	customer :				
Date :	06/07/2017	<b>Hour:</b> 16:23			
Company :					
Executed by VAB F Services	Fleet				
E-Mail :	@				
Signature authorized	by customer				