

BK1VE9

☒ EFFECTIVE
 ☐ NOT EXECUTED
 ☒ COLLECTION
 ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	137607 KM
File nr. :	1408406	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EDW362 / WF0HXXWPBHCL32254 /		yr of constructionr :	/
E-File nr. :		First registration :	01/11/2012
VFS-nr. :		Color :	GREY
Make + Model :	FORD / C-MAX	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ACERTA CVBA	Co2:	124g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	GR.C-MAX Trend St/St 95PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	95	kW:	70
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
	Warning triangle : OK [x]
First aid kit : OK [x]	Oil level : OK [x]
Jack, wheelspanner :	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4 /	Rim :		/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :	[x]	MISSING/INCOMPLETE	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	V
Rear tyre	215	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT THRESHOLD/LEFT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)	INT
[x]	WINDSCREEN/LEFT	WINDOW DAMAGE	HERSTELD
[x]	FRONT DOOR/RIGHT/REAR	DENT	
[x]	FRONT MUDGUARD/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	BONNET/CENTER/RIGHT/FRONT	DENT	
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE	+STEENSLAG

Interior

[x]	CENTER CONSOLE	SCRATCHED
[x]	SEAT FL	STAIN
[x]	DOOR IN REAR RIGHT	SCRATCHED
[x]	BOOT LID IN	SCRATCHED
[x]	BOOT IN L	SCRATCHED
[x]	BOOT IN R	SCRATCHED

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT	DENT		
		Repair paint - LI	New paint - E	Depr.
				Total
1	0 LU =0.00 EUR	211.80 EUR		50 %
				211.80 EUR
[x]	REAR LIGHT/RIGHT	HOLE/CRACK/TORN		
		Repair paint - LI	New paint - E	Depr.
				Total
1	10 LU =48.00 EUR	0 EUR		50 %
				48.00 EUR
[x]	REAR DOOR/RIGHT/RIGHT	DENT		+KRAS MET LAKSCHADE
		Repair paint - LI	New paint - E	Depr.
				Total
1	0 LU =0.00 EUR	301.68 EUR		50 %
				301.68 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	2	REAR LIGHT	90.00 EUR	50 %	180.00 EUR

1	2	3	4	5	6	7	8	9	10
741.48	0	0	0	0	0	0	0	0	0
370.74	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	741.48	0	741.48
HOG: 0	BG: 0		NA Deprec. 370.74
			0.00%
			TOTAL 370.74

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 06/07/2017 Hour : 15:18 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	