

BTV2PQ

☒ EFFECTIVE
 ☐ NOT EXECUTED
 ☒ COLLECTION
 ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	107114 KM
File nr. :	1416133	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1ERM164 / WDD2040001A847309 /		yr of constructionr :	/
E-File nr. :		First registration :	01/03/2013
VFS-nr. :		Color :	BLACK
Make + Model :	MERCEDES / C	Fuel type :	DIESEL
Object nr. :	12378	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	KEESING BELGIUM NV	Co2:	131g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	C BER 180 CDI BlueEFF. S&S 120PK	Country registration :	CHILE

VAT over the margin - car:	No	Metallic paint:	
Variant car:	BERLINE	Engine size:	2143
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	4
HP:	120	kW:	88
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK			Service manual :	OK	[x]	
Cert. of reg. / Part 1:				Cert. of conformity :	OK		
Cert. of reg. copy / Part 2:	OK	[x]		Insurance certificate :			
Warning vest :	OK	[x]		Transport licence :			
Tax certificate :				Navigation CD/SD/DVD			
Fuel card :				Car radio :	OK	[x]	
Mobile phone kit :				Extinguisher :	OK	[x]	
				Warning triangle :	OK	[x]	
First aid kit :	OK	[x]		Oil level :	OK	[x]	
Jack, wheelspanner :	OK	[x]		Filled up :	0		

Wheels and tyres: Summer tires

Wheel FL :	[x]	CONTINENTAL	Tyre :	OK	/	Rim :		/	Hubcap :		
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	CONTINENTAL	Tyre :	OK	/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	/	Rim :			/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK	/	Rim :			/	Hubcap :	

	[x]	Width	Height	Type	Rim	Index
Front tyre		225	45	R	17	W
Rear tyre		225	45	R	17	W

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] FRONT DOOR/LEFT/REAR

SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/CENTER/RIGHT

SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Others

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
211.80	190.00	0	0	0	0	0	0	0	0
105.90	190.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
190.00	211.80	0	401.80
HOG: 0	BG: 0		NA Deprec. 295.90
			0.00%
			TOTAL 295.90

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 08/07/2017 Hour : 13:27 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	