

[X] EFFECTIVE [ ] NOT EXECUTED

[ ] COLLECTION

[ ] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	171770 KM
File nr. :	1422750	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :	1DPO260 / ZAR94000007180406 /	Mileag ref. service :	0
E-File nr. :		yr of constructionr :	/
VFS-nr. :		First registration :	16/07/2012
Make + Model :	ALFA ROMEO / GIULIETTA	Color :	BROWN D
Object nr. :		Fuel type :	DIESEL
Classification :		Fuel :	
Customer company :	CBC BANQUE SA	Environment Class:	EURO 5
Driver :		Co2:	114g/km
Covering :	TISSUE	Remote controls:	2
Vehicle kind :	VEHICLE	Number keys :	2 [x]
Vehicle type :	GIULIETTA BER Distinct.Start&Stop 105PK	Seats (minivan) :	0
		Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
General condition:		Use:	Unknown

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:		[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK	[x]
Jack, wheelspanner :			Oil level :	OK	[x]
			Filled up :		0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :			/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark :

## Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)	POLIEREN
[x] REAR DOOR/CENTER/RIGHT	SCRATCH (WITHOUT PAINT DAMAGE)	POLIEREN

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x] REAR DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	+DEUK
	Repair paint - LI	New paint - E
3 0 LU =0.00 EUR	318.35 EUR	50 %
		318.35 EUR
[x] FRONT BUMPER/LEFT/CORNER	SCRATCH WITH PAINT DAMAGE	
	Repair paint - LI	New paint - E
2 0 LU =0.00 EUR	211.80 EUR	50 %
		211.80 EUR

### Others

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
95.00	211.80	318.35	0	0	0	0	0	0	0
95.00	105.90	159.18	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
95.00	530.15	0	625.15
HOG: 0	BG: 0		NA Deprec. 360.08
			0.00%
			TOTAL 360.08

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 24/07/2017	Hour : 09:23
Company :	
Executed by VAB Fleet Services	
E-Mail : @	
Signature authorized by customer	
	