

www.vabfleetservices.be Date: 24/07/2017 1/4

C0JVB6

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness:	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	69567 KM
File nr. :	1421316	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FJV289 / WBA3K91080F931	480 /	yr of constructionr :	/
E-File nr. :		First registration :	19/07/2013
VFS-nr. :		Color :	BROWN
Make + Model :	BMW / 3 TOURING	Fuel type :	DIESEL
Object nr. :	37226	Fuel:	
Classification:		Environment Class:	EURO 5
Customer company :	SBS SALES BELGIUM NV	Co2:	119g/km
Driver :		Remote controls:	1
Covering :	LEATHER	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	3 TOURING 316d 116PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes			
Variant car:	BREAK	Engine size:	1995			
Gear box :	Manueel	Number of places:	5			
Number of gears:	6	Number of doors:	5			
нр:	116	kW:	85			
Fisc HP		Imported vehicle:				
Animals transported:	No	Smoked in vehicle:	No			
Due date vehicle inspection:		Extra set of tires:	No			
		Use:	Unknown			
General condition:						



www.vabfleetservices.be Date: 24/07/2017 2/4

Original registr. number: OK Service manual:

Cert. of reg. / Part 1: Cert. of conformity: OK

Cert. of reg. copy / Part 2: OK
Warning vest: OK
Transport licence:

Tax certificate : Navigation CD/SD/DVD

Fuel card : Car radio : OK

Mobile phone kit : Extinguisher : OK

Warning triangle: OK

First aid kit: OK Oil level: OK [x]

Jack, wheelspanner: Filled up: 0

Wheels and tyres: Summer tires

ı	Wheel RES:		Tyre:		OK		/	Rim:	/	Hubcap:
ı	Wheel RR:	GOODYEAR	Tyre:		OK	[x]	2-4 /	Rim:	/	Hubcap:
ı	Wheel FR:	GOODYEAR	Tyre:	[x]	OK	[x]	2-4 /	Rim:	/	Hubcap:
ı	Wheel RL:	GOODYEAR	Tyre:		OK	[x]	2-4 /	Rim:	/	Hubcap:
ı	Wheel FL:	GOODYEAR	Tyre:		OK	[x]	2-4 /	Rim:	/	Hubcap:

[x] Width		Height	Туре	Rim	Index	
Front tyre	205	60	R	16	Н	
Rear tyre	205	60	R	16	Н	

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 24/07/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR DOOR/LEFT/CENTER DENT

[x] FRONT DOOR/LEFT/REAR DENT

FRONT MUDGUARD/LEFT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)

[x] BONNET/RIGHT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)

[x] FRONT MUDGUARD/RIGHT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/RIGHT/CORNER SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

1	2	3	4	5	6	7	8	9	10
211.80	0	0	0	0	0	0	0	0	0
105.90	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
0	211.80	0		211.80
HOG: 0	BG: 0		NA Deprec.	105.90

0.00%
TOTAL 105.90



www.vabfleetservices.be Date: 24/07/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMSTANCES			NORMAL CONCLUSION					
Extra Time :	0 min	Waiting time: 0 mi Reason:	n	Towing time : Reason :	0 min			
NOT EXECUTED Reason:	: No	I		<u> </u>				
Remark :								
Prices in EUR	without VAT							
Authorized by customer :			Executed by VAB Fleet So	ervices				
Remark authorized	d customer :							
Date :	24/07/2017	Hour: 16:08						
Company :								
Executed by VAB I Services	Fleet							
E-Mail:	@							
Signature authorized	d by customer		†					