

www.vabfleetservices.be Date: 14/07/2017 1/5

BW2AHB

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	112054 KM
File nr. :	1417796	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DPK645 / WBA1C91090J500	0003 /	yr of constructionr :	/
E-File nr. :		First registration :	13/07/2012
VFS-nr. :		Color :	SILVER
Make + Model :	BMW / 1	Fuel type :	DIESEL
Object nr. :		Fuel:	
Classification:		Environment Class:	EURO 5
Customer company:	KBC GROEP NV	Co2:	99g/km
Oriver :		Remote controls:	2
Covering:	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	1 HATCH 116d Eff.Dyn.Ed. 116PK	Country registration :	BELGIUM

Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
нр:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Metallic paint:

Yes



www.vabfleetservices.be Date: 14/07/2017 2/5

Original registr. number :	OK		Service manual :	NOK	[x] MISSING/INCOMPLETE
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest:	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres: Summer tires

	Rear	tyre			205					55			R		16		W	
	Fron	t tyre			205					55			R		16		W	
l			[x]		Width	1			Н	eight			Type		Rim		Index	
Wheel	I RES:	[x]			T	re:		OK		/	Rim:	[x]	MISSING/INCOMPLE	TE	/ Hubcap	:		
Wheel	IRR:	[x]	MICI	HELIN	T	re:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap	:		
Wheel	l FR :	[x]	MICI	HELIN	T	re:	[x]	OK	[x]	2-4 /	Rim:				/ Hubcap	:		
Wheel	l RL :	[x]	MICI	HELIN	T	re:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap	:		
Wheel	l FL:	[x]	MICI	HELIN	T	re:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap	:		

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

 [x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 14/07/2017 3/5

STATUS: ACCEPTABLE / USAGE DAMAGE

285.54

30	dywork \& windows							
x]	REAR BUMPER/CENTER/RIGHT			DENT		+KRAS	SSEN	
κ]	REAR WINDOW/LEFT			SCRATCH WITH P.	AINT DAMAGE			
k]	REAR DOOR/RIGHT/CENTER			DENT				
]	FRONT DOOR/LEFT/REAR			DENT				
	FRONT DOOR/RIGHT/REAR			DENT				
	FRONT DOOR/RIGHT/CENTER			DENT				
]	BONNET/CENTER/LEFT			DENT				
ŝΤ	TATUS: NOT ACCEPT	ABLE						
ВО	dywork \& windows							
]	FRONT BUMPER/LEFT			DENT				
	FRONT BUMPER/LEFT	Repair pa	int - LI	DENT New paint - E		Depr.		Total
	FRONT BUMPER/LEFT 1 0 LU =0.00 EUR	Repair pa 211.80 EU				Depr. 50 %		
			R		Unit price	50 %		
]	1 0 LU =0.00 EUR	211.80 EU	R		Unit price	50 % Depr.		211.80 EUR Total
	1 0 LU =0.00 EUR Number Code	211.80 EU Descriptio	R			50 % Depr.		211.80 EUR Total
(C)	1 0 LU =0.00 EUR Number Code 1 I 1 i-vab-kunst-01	211.80 EU Descriptio	R		110.64 EU	50 % Depr.		211.80 EUR Total
(C)	1 0 LU =0.00 EUR Number Code 1 I 1 i-vab-kunst-01 cessories and others	211.80 EU Descriptio	R on S REPAIR	New paint - E	110.64 EU	50 % Depr.		211.80 EUR Total
(C)	1 0 LU =0.00 EUR Number Code 1 I 1 i-vab-kunst-01 cessories and others	211.80 EU Descriptio	R on S REPAIR	New paint - E OTHER DAMAGES	110.64 EU	50 % Depr.		211.80 EUR Total 110.64 EUR
]	1 0 LU =0.00 EUR Number Code 1 I 1 i-vab-kunst-01 CCESSORIES and others FOG LAMPS	211.80 EU Descriptio PLASTICS Repair pa	R on S REPAIR	New paint - E OTHER DAMAGES	110.64 EU	50 % Depr. Depr.		211.80 EUR Total 110.64 EUR Total
]	1 0 LU =0.00 EUR Number Code 1 I 1 i-vab-kunst-01 CCESSORIES AND OTHERS FOG LAMPS 1 10 LU =48.00 EUR	211.80 EU Descriptio PLASTICS Repair pa	R on S REPAIR int - LI	New paint - E OTHER DAMAGES	110.64 EU	50 % Depr. Depr. 50 %		211.80 EUR Total 110.64 EUR Total
\ C (1 0 LU =0.00 EUR Number Code 1 I 1 i-vab-kunst-01 CCESSORIES and others FOG LAMPS 1 10 LU =48.00 EUR	Description PLASTICS Repair pa 0 EUR	R on S REPAIR int - LI	New paint - E OTHER DAMAGES	110.64 EU	50 % Depr. Depr. 50 % Depr.		211.80 EUR Total 110.64 EUR Total 48.00 EUR
:]	1 0 LU =0.00 EUR Number Code 1 I 1 i-vab-kunst-01 CCESSORIES and others FOG LAMPS 1 10 LU =48.00 EUR CCES Number Code	Description PLASTICS Repair pa 0 EUR	R on S REPAIR int - LI	New paint - E OTHER DAMAGES	Unit price	50 % Depr. Depr. 50 % Depr.	9	Total Total 48.00 EUR



www.vabfleetservices.be Date: 14/07/2017 4/5

		GENERAL	TRADITIONAL	INNOVATIVE
460.44		0	349.80	110.64
285.54	NA Deprec.		BG: 0	HOG: 0
	0.00%	-		
285.54	TOTAL			



Date: 5/5

14/07/2017 www.vabfleetservices.be [x] = Status Modification **Pictures:** No **CIRCUMSTANCES** NORMAL CONCLUSION Extra Time : $0 \min$ Waiting time: 0 min Towing time : $0 \min$ Reason: Reason: NOT EXECUTED: No Reason: Remark: Prices in EUR without VAT Authorized by Executed by VAB Fleet Services customer : Remark authorized customer : Date : 14/07/2017 Hour: 10:11 Company: Executed by VAB Fleet Services E-Mail: Signature authorized by customer