

CFIF7U

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	130768 KM
File nr. :	1432828	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DUF406 / YV1MW84F1C2682546 /		yr of constructionr :	/
E-File nr. :		First registration :	29/08/2012
VFS-nr. :		Color :	BLACK
Make + Model :	VOLVO / V50	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	EDF LUMINUS	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	V50 BRE DRIVe Start/Stop 99g 115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	114	kW:	84
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK	Insurance certificate :	
Warning vest :		Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	[x]
		Warning triangle :	OK
First aid kit :	[x]	Oil level :	OK
Jack, wheelspanner :	OK [x]	Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK	2-4 /	Rim :		Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	2-4 /	Rim :	WHEEL SCRATCHED	Hubcap :
Wheel FR :	[x]	PIRELLI	Tyre :	OK	2-4 /	Rim :		Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	2-4 /	Rim :		Hubcap :
Wheel RES:	[x]	ANDERE	Tyre :	OK	/	Rim :	MISSING/INCOMPLETE	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	REAR MUDGUARD/LEFT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR MUDGUARD/RIGHT/CENTER	DENT
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT
[x]	REAR DOOR/LEFT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	WINDSCREEN/CENTER/RIGHT	CHIPS
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS
[x]	FRONT BUMPER/CENTER/LEFT	CHIPS

Interior

[x]	SEAT FL	CARVED
-----	---------	--------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	FRONT MUDGUARD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE
-----	-----------------------------	---------------------------

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR

1	2	3	4	5	6	7	8	9	10
220.18	0	0	0	0	0	0	0	0	0
110.09	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	220.18	0	220.18
HOG: 0	BG: 0		NA Deprec. 110.09
			0.00%
			TOTAL 110.09

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 07/09/2017 Hour : 16:39 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	