

CHLVAC

☒ EFFECTIVE ☐ NOT EXECUTED ☐ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	43919 KM
File nr. :	1434499	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HUA998 / WVWZZZ6RZFY145635 /		yr of constructionr :	/
E-File nr. :		First registration :	02/10/2014
VFS-nr. :		Color :	GREY
Make + Model :	VOLKSWAGEN / POLO	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 6
Customer company :	ONBEKEND	Co2:	88g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1422
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	75	kW:	55
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6 /	Rim :		/	Hubcap :		
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6 /	Rim :		/	Hubcap :		
Wheel FR :	[x]	BRIDGESTONE	Tyre :	[x]	OK	[x]	4-6 /	Rim :	[x]	/	Hubcap :	[x] SCRATCHED
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6 /	Rim :		/	Hubcap :		
Wheel RES:	[x]		Tyre :	OK		/	Rim :		/	Hubcap :		

[x]	Width	Height	Type	Rim	Index
Front tyre	175	70	R	14	T
Rear tyre	175	70	R	14	T

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.
				Total
4	0 LU =0.00 EUR	246.56 EUR		50 %
				246.56 EUR
[x]	REAR MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE	+DEUK	
		Repair paint - LI	New paint - E	Depr.
				Total
5	0 LU =0.00 EUR	246.56 EUR		50 %
				246.56 EUR
[x]	BONNET/CENTER/LEFT	OTHER DAMAGES		
		Repair paint - LI	New paint - E	Depr.
				Total
3	0 LU =0.00 EUR	232.06 EUR		50 %
				232.06 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 2	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	29.16 EUR

HUB CAP FR

		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR

1	2	3	4	5	6	7	8	9	10
29.16	24.00	232.06	246.56	246.56	0	0	0	0	0
29.16	12.00	116.03	123.28	123.28	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
29.16	749.18	0	778.34
HOG: 0	BG: 1		NA Deprec. 403.75
			0.00%
			TOTAL 403.75

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 31/08/2017 Hour : 11:47 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	