

www.vabfleetservices.be Date: 11/09/2017 1/4

CJ10GP

### [X] EFFECTIVE [ ] NOT EXECUTED [X] COLLECTION [ ] DELIVERY

[x] = Status Modification

VAT over the margin - car:

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	72653 KM
File nr. :	1435614	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1JJG051 / WVWZZZAUZFP0	53143 /	yr of constructionr :	/
E-File nr. :		First registration :	02/01/2015
VFS-nr. :		Color :	GREY
Make + Model :	VOLKSWAGEN / GOLF	Fuel type :	DIESEL
Object nr. :	59040	Fuel:	
Classification:	E	Environment Class:	EURO 5
Customer company :	TECH MAHINDRA NETWORK SERVICES	Co2:	99g/km
Driver :		Remote controls:	2
Covering:	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan):	0
Vehicle type :		Country registration :	BELGIUM

Variant car:		Engine size:	1598			
Gear box :	Manueel	Number of places:	5			
Number of gears:	5	Number of doors:	5			
HP:	105	kW:	77			
Fisc HP		Imported vehicle:				
Animals transported:	No	Smoked in vehicle:	No			
Due date vehicle inspection:		Extra set of tires:	No			
		Use:	Unknown			
General condition:						

Metallic paint:

Yes



www.vabfleetservices.be Date: 11/09/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

### Wheels and tyres: Summer tires

		[x] W	idth			Не	eight		Туре		Rim	Index	1
Wheel RES:	[x]		Tyre:		OK		/	Rim:		/	Hubcap:		
Wheel RR:	[x]	CONTINENTAL	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:		
Wheel FR:	[x]	CONTINENTAL	Tyre:	[x]	OK	[x]	2-4 /	Rim:		/	<b>Hubcap:</b> [x]	SCRATCHED	
Wheel RL:	[x]	CONTINENTAL	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:		
Wheel FL:	[x]	CONTINENTAL	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:		

[x]	Width	Height	Туре	Rim	Index
Front tyre	195	65	R	15	Н
Rear tyre	195	65	R	15	Н

Remark:

#### Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 11/09/2017 3/4

#### STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/RIGHT

SCRATCH WITH PAINT DAMAGE

#### STATUS: NOT ACCEPTABLE

#### Bodywork \& windows

[x] FRONT BUMPER/LEFT SCRATCH WITH PAINT DAMAGE

 Repair paint - LI
 New paint - E
 Depr.
 Total

 1 0 LU = 0.00 EUR
 211.80 EUR
 50 %
 211.80 EUR

1	2	3	4	5	6	7	8	9	10
211.80	0	0	0	0	0	0	0	0	0
105.90	0	0	0	0	0	0	0	0	0

	GENERAL	TRADITIONAL	INNOVATIVE
211.80	0	211.80	0
NA Deprec. 105.90		BG: 0	HOG: 0
0.00%			

0.00% TOTAL 105.90



www.vabfleetservices.be Date: 11/09/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMS			NORMAL CONCLUSION						
Extra Time :	0 min	Waiting time: 0 min Reason:	n	Towing time : Reason :	0 min				
NOT EXECUTED Reason:	: No			1					
Remark :									
Prices in EUR	without VAT								
Authorized by customer:			Executed by VAB Fleet So	ervices					
Remark authorized	d customer :								
Date :	11/09/2017	<b>Hour:</b> 12:25							
Company :									
Executed by VAB I Services	Fleet								
E-Mail:	@								
Signature authorized	d by customer		1						