

www.vabfleetservices.be Date: 19/09/2017 1/4

COW4CM

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	136990 KM
File nr. :	1440159	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FJY444 / WBA3K11020F826	5080 /	yr of constructionr :	/
E-File nr. :		First registration :	22/07/2013
VFS-nr. :		Color :	SILVER
Make + Model :	BMW / 3 TOURING	Fuel type :	DIESEL
Object nr. :	6276	Fuel:	
Classification:	F	Environment Class:	EURO 5
Customer company:	LMS INTERNATIONAL NV	Co2:	119g/km
Driver :		Remote controls:	2
Covering:	IMITATION LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	3 TOURING 318d 136PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes			
Variant car:	BREAK	Engine size:	1995			
Gear box :	Manueel	Number of places:	5			
Number of gears:	6	Number of doors:	5			
нр:	136	kW:	100			
Fisc HP		Imported vehicle:				
Animals transported:	No	Smoked in vehicle:	No			
Due date vehicle inspection:		Extra set of tires:	No			
		Use:	Unknown			
General condition:						



Date: 19/09/2017 www.vabfleetservices.be 2/4

Original registr. number :	OK		Service manual :		
Cert. of reg. / Part 1:			Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate:			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICI	HELIN	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap :	
Wheel RL:	[x]	MICI	HELIN	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel FR:	[x]	MICI	HELIN	Tyre:	[x]	OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel RR:	[x]	MICI	HELIN	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel RES:	[x]			Tyre:		OK		/	Rim:		/	Hubcap:	
		_											
		[x]	Wid	dth			Не	ight		Туре		Rim	Index
Fron	t tyre		20)5				60		R		16	Н

	Index
Front tyre 205 60 R 16	Н
Rear tyre 205 60 R 16	Н

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 19/09/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

[x] FRONT DOOR/RIGHT/CENTER

SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] ROOF STYLE/FRONT/LEFT/CENTER

OTHER DAMAGES

SLECHTE HERSTELLING

Number Code Description Unit price Depr. Total

0

[x] FRONT BUMPER/RIGHT

SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

1	2	3	4	5	6	7	8	9	10
211.80	0	0	0	0	0	0	0	0	0
105.90	0	0	0	0	0	0	0	0	0

	GENERAL	TRADITIONAL	INNOVATIVE
211.80	0	211.80	0
NA Deprec. 105.90		BG: 0	HOG: 0
0.000/			

0.00%
TOTAL 105.90



19/09/2017 Date: www.vabfleetservices.be 4/4

[x] = Status Modification

Pictures: No)						
CIRCUMS	TANCES		NORMAL CONCLUSION				
Extra Time :	0 min	Waiting time: 0 mi Reason:	in	Towing time : Reason :	0 min		
NOT EXECUTED :	: No	I					
Remark :							
Prices in EUR v	vithout VAT						
Authorized by customer :			Executed by VAB Fleet Se	ervices			
Remark authorized	customer :						
Date :	19/09/2017	Hour: 16:31					
Company :							
Executed by VAB F Services	leet						
E-Mail:	@						
Signature authorized	by customer						