

www.vabfleetservices.be Date: 13/09/2017 1/6

CKZJU5

## [X] EFFECTIVE [ ] NOT EXECUTED [X] COLLECTION [ ] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	81761 KM
File nr. :	1437166	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DVL996 / WBAVN71020VX	7,00293 /	yr of constructionr :	/
E-File nr. :		First registration :	10/09/2012
VFS-nr. :		Color :	BROWN
Make + Model :	BMW / X1	Fuel type :	DIESEL
Object nr. :		Fuel:	
Classification:		Environment Class:	EURO 5
Customer company :	KBC BANK NV	Co2:	128g/km
Oriver :		Remote controls:	2
Covering:	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	X1 sDrive18 136PK	Country registration :	BELGIUM

Variant car:	SUV	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:		I	

Metallic paint:

Yes



www.vabfleetservices.be Date: 13/09/2017 2/6

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

## Wheels and tyres: Summer tires

		[x]	Width			He	eight		Type		Rim	Index
Wheel RES:	[x]	ANDERE	Tyre:		OK		/	Rim:		/	Hubcap:	
Wheel RR:	[x]	MICHELIN	Tyre:		OK	[x]	4-6 /	Rim:		/	Hubcap: [2	s] SCRATCHED
Wheel FR:	[x]	MICHELIN	Tyre:	[x]	OK	[x]	2-4 /	Rim:		/	Hubcap: [2	SCRATCHED
Wheel RL:	[x]	MICHELIN	Tyre:		OK	[x]	4-6 /	Rim:		/	Hubcap: [2	SCRATCHED
Wheel FL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap: [2	SCRATCHED

[x] Width		Height	Туре	Rim	Index
Front tyre	225	50	R	17	Н
Rear tyre	225	50	R	17	Н

Remark: REP. KIT OK

## Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

 [x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



Date: 13/09/2017 3/6 www.vabfleetservices.be

### Conclusion

ROOF/FRONT/CENTER/RIGHT OTHER DAMAGES OVBH POL.

CELED A CE

### STATUS: ACCEPTABLE / USAGE DAMAGE

<b>Body</b>	work	\& win	dows
-------------	------	--------	------

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE
[44]	REFIRED COM ENCEPTIFICEER I	BERRITER WITH THE TENENCE

REAR DOOR/CENTER/LEFT SCRATCH (WITHOUT PAINT DAMAGE) OVBH POL. [x]

REAR DOOR/LEFT/CENTER SCRATCH (WITHOUT PAINT DAMAGE) POL. [x]

REAR DOOR/RIGHT/REAR SCRATCH (WITHOUT PAINT DAMAGE) POL. [x]

[x] REAR DOOR/RIGHT/CENTER DENT +KRAS

[x] FRONT DOOR/LEFT/REAR SCRATCH WITH PAINT DAMAGE

FRONT DOOR/RIGHT/REAR [x] DENT

FRONT DOOR/RIGHT/CENTER SCRATCH (WITHOUT PAINT DAMAGE) OVBH POL.

FRONT MUDGUARD/LEFT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)

#### Interior

[x] SEAT FR **STAIN** 

#### Accessories and others

DOORHANDLE SCRATCH (WITHOUT PAINT DAMAGE) [x]

OUTSIDE MIRROR LEFTHAND SIDE SCRATCH (WITHOUT PAINT DAMAGE)

### STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[X]	REAR WINDOW/RIGHT		WINDOW DAMAGE	GEKRAST	
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	0 EUR		50 %	

REAR MUDGUARD/RIGHT/CENTER		SCRATCH WITH PAINT DA	SCRATCH WITH PAINT DAMAGE				
	Repair paint - LI	New paint - E	Depr.	Total			
5 0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR			



Date: 13/09/2017 4/6 www.vabfleetservices.be REAR DOOR/RIGHT/FRONT DENT [x] Number Code Description Unit price Depr. Total I 1 BEAT OUT DENT 63.00 EUR 63.00 EUR i-vab-uitd-01 Interior SEAT REAR L [x] STAIN Number Code Description Unit price Depr. Total CLEANING (PER 15') I 1 14.58 EUR 14.58 EUR i-vab-rein-07 **Others** HUB CAP FL Repair paint - LI New paint - E **Total** Depr. 3 0 LU =0.00 EUR 50 % HUB CAP REAR L Repair paint - LI New paint - E Depr. Total 3 0 LU =0.00 EUR 50 % HUB CAP REAR RIGHT Repair paint - LI New paint - E Depr. Total 3 0 LU =0.00 EUR 50 % HUB CAP FR Repair paint - LI New paint - E Depr. Total 3 0 LU =0.00 EUR 50 % **Pieces** Number Code Description Unit price Total Depr. BACK WINDOW 250.00 EUR 250.00 EUR 50 % Number Code Description Unit price Total Depr. WHEEL CAP 30.00 EUR 50 % 30.00 EUR Number Code Description Unit price Total Depr. WHEEL CAP 30.00 EUR 50 % 30.00 EUR Number Code Description Unit price Depr. Total WHEEL CAP 30.00 EUR 50 % 30.00 EUR Number Code Description Unit price Depr. **Total** WHEEL CAP 30.00 EUR 30.00 EUR 50 %



www.vabfleetservices.be Date: 13/09/2017 5/6

1	2	3	4	5	6	7	8	9	10
250.00	14.58	120.00	63.00	308.20	0	0	0	0	0
125.00	14.58	60.00	63.00	154.10	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
755.78		0	678.20	77.58
416.68	NA Deprec.		BG: 0	HOG: 0
	0.00%			
416.68	TOTAL			



www.vabfleetservices.be Date: 13/09/2017 6/6

[x] = Status Modification

Pictures: No

rictures: No	O .						
CIRCUMSTANCES		NORMAL CONCLUSION					
Extra Time :	0 min	Waiting time : (Reason :	) min	Towing time : Reason :	0 min		
NOT EXECUTED Reason:	: No	I		I			
Remark :	NAVI OK [x]						
Prices in EUR	without VAT						
Authorized by customer :			Executed by VAI	Executed by VAB Fleet Services			
Remark authorized	l customer :						
Date : Company :	13/09/2017	<b>Hour:</b> 12:22					
Executed by VAB I Services	Fleet						
E-Mail:	@						
Signature authorized	l by customer						