

www.vabfleetservices.be Date: 13/09/2017 1/4

CEVQZ8

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Vehicle type:

Commissionar: **KBC REMARKETING** Cleanliness: INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 144021 KM File nr. : Mileage start / arrival: 0 / 01432315 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1FIL811 / WDD2042021G163564 / E-File nr. : First registration: 08/07/2013 VFS-nr.: Color: **BLUE** Make + Model : Fuel type : MERCEDES / C BREAK **DIESEL** Object nr. : Fuel: **Environment Class:** Classification: EURO 5 Customer company: Co2: BELGACOM INS/FLEET NV 114g/km Driver : Remote controls: PARTIAL LEATHER Covering: Number keys: 1 [x] Vehicle kind: VEHICLE Seats (minivan): 0

Country registration:

BELGIUM

C BRE 220CDI BE Edition Avantgarde 163PK

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	2143
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	163	kW:	120
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			



13/09/2017 Date: www.vabfleetservices.be 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :		
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

Fron	Front tyre		205			55				R 16		16	V	
[x]		[x]	V	Vidth		Height				Туре		Rim	Index	
Wheel RES:	[x]	ANI	DERE	Tyre:		OK		/	Rim :				/ Hubcap:	
Wheel RR:	[x]	VRE	EDESTEIN	Tyre:		OK	[x]	4-6 /	Rim:	[x]			/ Hubcap:	
Wheel FR:	[x]	MIC	HELIN	Tyre:	[x]	OK	[x]	4-6 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel RL:	[x]	VRE	EDESTEIN	Tyre:		OK	[x]	4-6 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel FL:	[x]	MIC	HELIN	Tyre:		OK	[x]	4-6 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	

[x] Width	Height	Туре	Rim	Index
Front tyre 205	55	R	16	V
Rear tyre 205	55	R	16	V

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 13/09/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR DOOR/LEFT/REAR SCRATCH WITH PAINT DAMAGE RAND

SCRATCH WITH PAINT DAMAGE INSTAP

[x] REAR DOOR/RIGHT/FRONT DENT

STATUS: NOT ACCEPTABLE

REAR THRESHOLD/LEFT/REAR

Others

[x]

RIM REAR LEFT

]	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

	1	2	3	4	5	6	7	8	9	10
95	5.00	0	0	0	0	0	0	0	0	0
95	.00	0	0	0	0	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
95.00		0	0	95.00
95.00	NA Deprec.		BG: 0	HOG: 0
	0.00%			
95.00	TOTAL			



www.vabfleetservices.be Date: 13/09/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time :	0 min	Waiting tin Reason :	ne: 0 min		Towing time : Reason :	0 min
NOT EXECUTED : Reason :	No					
Remark :	,					
Prices in EUR v	vithout VAT					
Authorized by customer :				Executed by VAB Flee	et Services	
Remark authorized	customer :					
Date :	13/09/2017	Hour :	15:14			
Company:						
Executed by VAB F. Services	leet					
E-Mail :	@					
Signature authorized	by customer					