

www.vabfleetservices.be Date: 22/09/2017 1/4

CQYP50

X] EFFECTIVE	[ ] NOT EXECUTED	[ ] COLLECTION	[ ] DELIVERY
--------------	------------------	----------------	--------------

[x] = Status Modification

Commissionar: **KBC REMARKETING** Cleanliness: INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 38410 KM File nr. : Mileage start / arrival: 0 / 01441784 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1PDZ612 / YV1FW74C1G1325143 / E-File nr. : First registration: 01/01/1918 VFS-nr.: Color: **BLACK** Make + Model : Fuel type : VOLVO / V60

Object nr.: ONBEKEND Fuel:

Classification : Environment Class:

Customer company: ONBEKEND Co2: g/km

Driver: Remote controls: 1

Covering: TISSUE Number keys:  $1 \lceil \chi \rceil$ 

Vehicle kind: VEHICLE Seats (minivan): 0

Vehicle type : Country registration : BELGIUM

Metallic paint: VAT over the margin - car: Yes **BREAK** Engine size: Variant car: Gear box : Number of places: 5 Manueel Number of gears: 6 Number of doors: 5 HP: kW: Fisc HP Imported vehicle: No Smoked in vehicle: Animals transported: No No Due date vehicle inspection: Extra set of tires: No

Use: Unknown

General condition:



22/09/2017 Date: www.vabfleetservices.be 2/4

Original registr. number :	Service manual: OK [x]
Cert. of reg. / Part 1:	Cert. of conformity:
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest: OK [x]	Transport licence :
Tax certificate :	Navigation CD/SD/DVD OK [x]
Fuel card :	Car radio: OK [x]
Mobile phone kit :	Extinguisher: OK [x]
	Warning triangle: OK [x]
First aid kit: OK [x]	Oil level: OK [x]
Jack, wheelspanner :	Filled up: 0

### Wheels and tyres: Summer tires

Fron	t tyre			215				55		R		16	V
		[x]		Width			He	eight		Type		Rim	Index
Wheel RES:	[x]			Tyre:		OK		/	Rim:		/	Hubcap:	
Wheel RR:	[x]	MIC	HELIN	Tyre:		OK	[x]	4-6 /	Rim:		/	Hubcap:	
Wheel FR:	[x]	MIC	HELIN	Tyre:	[x]	OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel RL:	[x]	MIC	HELIN	Tyre:		OK	[x]	4-6 /	Rim:		/	Hubcap:	
Wheel FL:	[x]	MIC	HELIN	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap :	

[x]	Width	Height	Туре	Rim	Index
Front tyre	215	55	R	16	V
Rear tyre	215	55	R	16	V

Remark:

### Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 22/09/2017 3/4

#### STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork	<b>\&amp;</b> windows
----------	-----------------------

[x] REAR DOOR/LEFT/CENTER

SCRATCH WITH PAINT DAMAGE

#### STATUS: NOT ACCEPTABLE

#### Bodywork \& windows

[x] REAR MUDGUARD/LEFT/FRONT

SCRATCH WITH PAINT DAMAGE

+DEUK

Depr. Total

1 0 LU =0.00 EUR 308.20 EUR

Repair paint - LI

50 % 308.20 EUR

#### Interior

[x] FLOOR BOOT

DIRTY

New paint - E

	Number	Code	Description	Unit	price De	epr.	Total
2	I 1	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58	B EUR		14.58 EUR

1	2	3	4	5	6	7	8	9	10
308.20	14.58	0	0	0	0	0	0	0	0
154.10	14.58	0	0	0	0	0	0	0	0

	GENERAL	TRADITIONAL	INNOVATIVE
322.78	0	308.20	14.58
NA Deprec. 168.68		BG: 0	HOG: 0
0.00%			

0.00% TOTAL 168.68



22/09/2017 Date: www.vabfleetservices.be 4/4

[x] = Status Modification

Pictures: No

CIRCUMSTANCES				UNDER CONDITION - VEHICLE WET				
Extra Time :	0 min	Waiting tim Reason :	Waiting time: 0 min Reason:		Towing time : Reason :	0 min		
NOT EXECUTED : Reason :	No	<u> </u>			<b>.</b>			
Remark:	,							
Prices in EUR w	rithout VAT							
Authorized by customer :				Executed by VAB F	Fleet Services			
Remark authorized	customer :							
Date :	22/09/2017	Hour:	10:20					
Company:								
Executed by VAB Fl Services	eet							
E-Mail :	@							
Signature authorized l	by customer			1				