

www.vabfleetservices.be Date: 25/09/2017 1/4

CP1JVZ

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Commissionar: KBC REMARKETING Cleanliness: INT: CLEAN [x] EXT: CLEAN [x]

Owner: 71648 KM

File nr.: 1440286 Mileage start / arrival: 0 / 0

Reg number / Chassis / Ref: 0

1FLS159 / YV1FS8481E2278471 / yr of constructionr: /

E-File nr.: First registration: 08/08/2013

VFS-nr.: Color: GREY

Make + Model: VOLVO / S60 Fuel type: DIESEL

Object nr.: 33123 Fuel:

Classification: Environment Class: EURO 5

Customer company: HUNTSMAN EUROPE BVBA Co2: 103g/km

Driver: Remote controls: 2

Covering: TISSUE Number keys: 2[x] Vehicle kind: VEHICLE Seats (minivan): 0

 Vehicle type :
 S60 BER D2 Kinetic 115PK
 Country registration :
 BELGIUM

Metallic paint: VAT over the margin - car: No Yes BERLINE 1560 Variant car: Engine size: Gear box : Number of places: 5 Manueel Number of gears: 6 Number of doors: 4 HP: kW: 114 84 Fisc HP Imported vehicle: Animals transported: No Smoked in vehicle: No Due date vehicle inspection: Extra set of tires: No

Use:

Unknown

General condition:



www.vabfleetservices.be Date: 25/09/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELI	Tyre:		OK	[x]	2-4 /	Rim:				Hubcap :	
Wheel RL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	Hubcap:	
Wheel FR:	[x]	MICHELIN	Tyre:	[x]	OK	[x]	2-4 /	Rim:				Hubcap:	
Wheel RR:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:				Hubcap:	
Wheel RES:	[x]		Tyre:		OK		/	Rim:				Hubcap:	
		[x]	Width			He	eight			Туре		Rim	Index
Fre	nt tyre		205			(60			R		16	Н
Re	ar tvre		205			- (60			R		16	Н

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

 [x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



Date: 25/09/2017 3/4 www.vabfleetservices.be

DENT

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR DOOR/CENTER/LEFT

REAR BUMPER/RIGHT/CORNER SCRATCH WITH PAINT DAMAGE [x]

STATUS: NOT ACCEPTABLE

		Repair paint - LI	New paint - E	Depr.	Total
[X]	ROOF/CENTER/LEFT		OTHER DAMAGES	CHEMISCHE INV	WERKING

1 0 LU =0.00 EUR 481.50 EUR 50 % 481.50 EUR

[x] BONNET/CENTER/RIGHT/FRONT OTHER DAMAGES

Repair paint - LI

1 0 LU =0.00 EUR

New paint - E

Depr.

TOTAL

Total

480.79

290.08 EUR 50 % 290.08 EUR

Others

RIM REAR LEFT

]	Number	Code	Description	Unit price	Depr.	Total
2.	I 1	i-vah-herstalu-02	REPAIR ALLOY WHEEL	95 00 EUR		95 00 EUR

1	2	3	4	5	6	7	8	9	10
771.58	95.00	0	0	0	0	0	0	0	0
385.79	95.00	0	0	0	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
866.58		0	771.58	95.00
480.79	NA Deprec.		BG: 0	HOG: 0
	0.00%			



25/09/2017 Date: www.vabfleetservices.be 4/4

[x] = Status Modification

Pictures: No										
CIRCUMST	TANCES		NORMAL CONCLUSION							
Extra Time :	0 min	Waiting time : Reason :	0 min		Towing time : Reason :	0 min				
NOT EXECUTED :	No	I								
Remark :										
Prices in EUR wi	ithout VAT									
Authorized by customer:				Executed by VAB Fleet Se	rvices					
Remark authorized c	ustomer :									
Date :	25/09/2017	Hour : 12	2:08							
Company :										
Executed by VAB Fle Services	eet									
E-Mail :	@									
Signature authorized b	y customer									