

CQW0IX

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	89517 KM
File nr. :	1441739	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DSH743 / WBA3D11090J618057 /		yr of constructionr :	/
E-File nr. :		First registration :	09/08/2012
VFS-nr. :		Color :	RED
Make + Model :	BMW / 3	Fuel type :	DIESEL
Object nr. :	8050	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	G4S CASH SOLUTIONS (BELGIUM) NV	Co2:	116g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	3 BER 318d Bus.Ed. 136PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:	
--------------------	--

Original registr. number :	OK	Service manual :	
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK [x]	Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK [x]
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
		Warning triangle :	OK [x]
First aid kit :	OK [x]	Oil level :	OK [x]
Jack, wheelspanner :		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :	[x]	MISSING/INCOMPLETE	
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :	[x]	MISSING/INCOMPLETE	
Wheel FR :	[x]	BRIDGESTONE	Tyre :	[x]	OK	[x]	2-4 /	Rim :	/	Hubcap :	[x]	MISSING/INCOMPLETE
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :	[x]	MISSING/INCOMPLETE	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	W
Rear tyre	205	60	R	16	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR MUDGUARD/RIGHT/CENTER DENT

[x] FRONT BUMPER/RIGHT DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR DOOR/CENTER/LEFT	OTHER DAMAGES	CHEMISCHE INWERKING	
		Repair paint - LI	New paint - E	Depr. Total
6	0 LU =0.00 EUR	301.68 EUR	50 %	301.68 EUR
[x]	REAR MUDGUARD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	+DEUK	
		Repair paint - LI	New paint - E	Depr. Total
5	0 LU =0.00 EUR	308.20 EUR	50 %	308.20 EUR
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	+DEUK	
		Repair paint - LI	New paint - E	Depr. Total
7	0 LU =0.00 EUR	318.35 EUR	50 %	318.35 EUR
[x]	REAR THRESHOLD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	+DEUK	
		Repair paint - LI	New paint - E	Depr. Total
8	0 LU =0.00 EUR	310.50 EUR	50 %	310.50 EUR
[x]	FRONT THRESHOLD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE	+DEUK	
		Repair paint - LI	New paint - E	Depr. Total
4	0 LU =0.00 EUR	310.50 EUR	50 %	310.50 EUR
[x]	FRONT DOOR/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE	+DEUKEN	
		Repair paint - LI	New paint - E	Depr. Total
3	0 LU =0.00 EUR	318.35 EUR	50 %	318.35 EUR
[x]	WINDSCREEN/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr. Total
2	0 LU =0.00 EUR	0 EUR	50 %	
		Repair paint - LI	New paint - E	Depr. Total
2	25 LU =120.00 EUR	0 EUR	50 %	120.00 EUR

[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
9	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	BONNET/CENTER/RIGHT/FRONT	OTHER DAMAGES		CHEMISCHE INWERKING	
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR

Others					
	CLEANLINESS INTERIOR				
Number	Code	Description	Unit price	Depr.	Total
10	I 2	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	29.16 EUR
	HUB CAP FL				
		Repair paint - LI	New paint - E	Depr.	Total
10	0 LU =0.00 EUR			50 %	
	HUB CAP REAR L				
		Repair paint - LI	New paint - E	Depr.	Total
10	0 LU =0.00 EUR			50 %	
	HUB CAP REAR RIGHT				
		Repair paint - LI	New paint - E	Depr.	Total
10	0 LU =0.00 EUR			50 %	
	HUB CAP FR				
		Repair paint - LI	New paint - E	Depr.	Total
10	0 LU =0.00 EUR			50 %	

Pieces					
Number	Code	Description	Unit price	Depr.	Total
2	1	WIND SCREEN	367.20 EUR	50 %	367.20 EUR
Number	Code	Description	Unit price	Depr.	Total
10	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
10	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
10	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
10	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
290.08	487.20	318.35	310.50	308.20	301.68	318.35	310.50	318.35	149.16
145.04	243.60	159.18	155.25	154.10	150.84	159.18	155.25	159.18	89.16

INNOVATIVE	TRADITIONAL	GENERAL	
29.16	3083.21	0	3112.37
HOG: 0	BG: 0		NA Deprec. 1570.76
			0.00%
			TOTAL 1570.76

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 25/09/2017 Hour : 08:27 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	