

www.vabfleetservices.be Date: 22/09/2017 1/4

COVRXO

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

Commissionar :	KBC REMARKETING	Cleanliness:	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	89906 KM
File nr. :	1440153	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FPQ748 / WBA3D91060J412	2841 /	yr of constructionr :	/
E-File nr. :		First registration :	17/09/2013
VFS-nr. :		Color :	BLUE
Make + Model :	BMW / 3	Fuel type :	DIESEL
Object nr. :	35450	Fuel:	
Classification:		Environment Class:	EURO 5
Customer company:	CGI NV/SA	Co2:	114g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	3 BER 316d 116PK	Country registration :	BELGIUM

		1	
Variant car:	BERLINE	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	4
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:		I	

Metallic paint:

Yes



www.vabfleetservices.be Date: 22/09/2017 2/4

Original registr. number: OK Service manual:

Cert. of reg. / Part 1: OK [x] Cert. of conformity: OK

Cert. of reg. copy / Part 2: Insurance certificate :

Warning vest : Transport licence :

Tax certificate : Navigation CD/SD/DVD

Fuel card: Car radio: OK [x]

Mobile phone kit: Extinguisher: OK [x]

Warning triangle: OK [x]

0

First aid kit: OK [x] Oil level: OK [x]

Jack, wheelspanner : Filled up :

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	/	Hubcap:
Wheel FR:	[x]	MICHELIN	Tyre:	[x]	OK	[x]	2-4 /	Rim:			/	Hubcap:
Wheel RR:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:			/	Hubcap:
Wheel RES:	[x]		Tyre:		OK		/	Rim:			/	Hubcap:

[x] Width		Height	Туре	Rim	Index
Front tyre	205	60	R	16	W
Rear tyre	205	60	R	16	W

Remark:

Wheels and tyres:

1						
	Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
	Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
	Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
	Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
	Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 22/09/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/SIDE/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

[x] FRONT DOOR/RIGHT/REAR DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR DOOR/LEFT/FRONT DENT

]	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

[X] FRONT DOOR/LEFT/CENTER SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	318.35 EUR	'	50 %	318.35 EUR

1	2	3	4	5	6	7	8	9	10
318.35	63.00	0	0	0	0	0	0	0	0
159.18	63.00	0	0	0	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
381.35		0	318.35	63.00
222.18	NA Deprec.		BG: 0	HOG: 0
	0.00%			
222.18	TOTAL			



www.vabfleetservices.be Date: 22/09/2017 4/4

[x] = Status Modification

Pictures: No

CES	NORMAL CONCLUSION					
) min	Waiting tin Reason :	ne: 0 min		Towing time : Reason :	0 min	
No						
VAT						
			Executed by VAB	Fleet Services		
:						
9/2017	Hour:	15:31				
er						
	EES) min No VAT : er	O min Reason: VAT Hour:	Waiting time: 0 min Reason: No Hour: 15:31	Waiting time: 0 min Reason: VAT Executed by VAB 1 : 0/2017 Hour: 15:31	Waiting time: 0 min Reason: No Watting time: Reason: Reason: Reason: Executed by VAB Fleet Services Hour: 15:31	