

www.vabfleetservices.be Date: 27/09/2017 1/5

CSJ79H

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness:	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	141287 KM
File nr. :	1443017	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DRZ506 / WBA3D11060J618	8422 /	yr of constructionr :	/
E-File nr. :		First registration :	07/08/2012
VFS-nr. :		Color :	BLACK
Make + Model :	BMW / 3	Fuel type :	DIESEL
Object nr. :		Fuel:	
Classification:		Environment Class:	EURO 5
Customer company :	EDF LUMINUS	Co2:	118g/km
Driver :		Remote controls:	2
Covering:	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	3 BER 318d 136PK	Country registration :	RFI GILIM

VAT over the margin - car:	No	Metallic paint:	Yes					
Variant car:	BERLINE	Engine size:	1995					
Gear box :	Manueel	Number of places:	5					
Number of gears:	6	Number of doors:	4					
HP:	136	kW:	100					
Fisc HP		Imported vehicle:						
Animals transported:	No	Smoked in vehicle:	No					
Due date vehicle inspection:		Extra set of tires:	No					
		Use:	Unknown					
General condition:								



www.vabfleetservices.be Date: 27/09/2017 2/5

Original registr. number :	OK		Service manual :		
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres: Summer tires

Whee	el FL:	[x]	BRII	DGESTONE	Tyre:		OK	[x]	2-4 /	Rim:				/ Hubcap:	
Whee	el RL :	[x]	BRII	DGESTONE	Tyre:		OK	[x]	1.6-2 /	Rim:				/ Hubcap:	
Whee	el FR:	[x]	BRII	DGESTONE	Tyre:	[x]	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Whee	el RR:	[x]	BRII	DGESTONE	Tyre:		OK	[x]	1.6-2 /	Rim:				/ Hubcap:	
Whee	el RES:	[x]	ANI	DERE	Tyre:		OK	[x]	/	Rim:				/ Hubcap:	
			[x]	W	idth	Т		Н	eight	I		Туре		Rim	Index
	Fron	t tyre		2	225				55			R		16	W
	Rear	r tvre		2	225				55			R		16	W

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

 [x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 27/09/2017 3/5

STATUS: ACCEPTABLE / USAGE DAMAGE

Boo	lywork \& windows	
[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	REAR MUDGUARD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT
[x]	THRESHOLD FRONT/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE SLUITKANT
[x]	FRONT MUDGUARD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS
[x]	REAR DOOR/LEFT/LEFT	SCRATCH WITH PAINT DAMAGE
Inte	rior	
[x]	SEAT FR	SCRATCHED

STATUS: NOT ACCEPTABLE

REAR BUMPER /LEFT/CORNER		SCRATCH WITH PAINT DAMAGE		
	Repair paint - LI	New paint - E	Depr.	Total
6 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUI
REAR DOOR/LEFT/CENTER		SCRATCH WITH PAINT DAMAGE		
	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
WINDSCREEN/CENTER/LEFT		WINDOW DAMAGE		
	Repair paint - LI	New paint - E	Depr.	Total
5 25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR
FRONT BUMPER/RIGHT/CORNER		SCRATCH WITH PAINT DAMAGE		
	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR



www.vabfleetservices.be Date: 27/09/2017 4/5

nterior									
x] DOO	R IN REAR L				CUT / TORN				
			Repair pain	at - LI	New paint - E		Depr.		Total
1 5 LU	=24.00 EUR		0 EUR				50 %		24.00 EUR
Accesso	ories and oth	ers							
x] OUT	SIDE MIRROR LEFT	HAND SIDE			SCRATCH WITH	PAINT DAMAGI	Ξ		
Num	ber Code		Description			Unit pri	ce Depr.		Total
4 I	1 i-vab-sp-01		SPOTREPA	IR		115.56 E	EUR		115.56 EUR
Others									
RIM	FRONT RIGHT								
Num	ber Code		Description			Unit pri	ce Depr.		Total
7 I	i-vab-herstalu-02	2	REPAIR AL	LOY WHEEL		95.00 EU	JR		95.00 EUR
Pieces									
Num	ber Code		Description			Unit pri	ce Depr.		Total
1	UPHOLSTERY	DOOR				90.00 EU	JR 50 %		90.00 EUR
Num	ber Code		Description			Unit pri	ce Depr.		Total
5	WIND SCREEN					367.20 E	EUR 50 %		367.20 EUR
1	2	3	4	5	6	7	8	9	10
114.00	211.80	318.35	115.56	487.20	211.80	95.00	0	0	0
57.00	105.90	159.18	115.56	243.60	105.90	95.00	0	0	0
IN	NOVATIVE	TRADI	TIONAL	1	GENERAL				
	210.56	134	43.15		0				1553.71
	HOG: 0	В	G: 0			NA Dep	rec.		882.1
				-		0.00%	ó	1	
						TOTA	L	1	882.14



www.vabfleetservices.be Date: 27/09/2017 5/5

[x] = Status Modification

Pictures: No

CIDCLING									
CIRCUMS	IANCES	NORMAL CONCLUSION							
Extra Time :	0 min	Waiting time: 0 mi Reason:	n	Towing time : Reason :	0 min				
NOT EXECUTED : Reason :	No	I							
Remark:	NAVI OK [x]								
Prices in EUR w	rithout VAT								
Authorized by customer :			Executed by VAB Fleet Se	ervices					
Remark authorized	customer :								
Date :	27/09/2017	Hour: 09:47							
Company :									
Executed by VAB Fl Services	eet								
E-Mail :	@								
Signature authorized l	by customer								