

CQ8S6F

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	158270 KM
File nr. :	1441208	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HEY003 / WBA5J11050D336191 /		yr of constructionr :	/
E-File nr. :		First registration :	03/07/2014
VFS-nr. :		Color :	SILVER
Make + Model :	BMW / 5 TOURING	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :	L	Environment Class:	EURO 6
Customer company :	Delaware Consulting CVBA	Co2:	127g/km
Driver :		Remote controls:	2
Covering :	IMITATION LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:	
--------------------	--

Original registr. number :	OK		Service manual :	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	NOK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
			Warning triangle :	OK [x]
First aid kit :	OK	[x]	Oil level :	OK [x]
Jack, wheelspanner :			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :		/	Hubcap :			
Wheel RL :	[x]	KLÉBER	Tyre :	OK	[x]	>6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :		
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RR :	[x]	KLÉBER	Tyre :	OK	[x]	>6 /	Rim :		/	Hubcap :			
Wheel RES:	[x]	ANDERE	Tyre :	OK		/	Rim :		/	Hubcap :			

	[x]	Width	Height	Type	Rim	Index
Front tyre		225	55	R	17	Y
Rear tyre		225	55	R	17	Y

Remark :	REP. KIT OK
-----------------	-------------

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/CENTER/LEFT	OTHER DAMAGES	
[x]	REAR BUMPER/SIDE/LEFTCENTER	SCRATCH WITH PAINT DAMAGE	
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	KRAS + DEEL TE POL.
[x]	REAR DOOR/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE	+DEUKJE
[x]	WINDSCREEN/LEFT	WINDOW DAMAGE	REEDS HERSTELD
[x]	WINDSCREEN/RIGHT	CHIPS	
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS	
[x]	FRONT/LEFT	SCRATCH WITH PAINT DAMAGE	

Accessories and others

[x]	FUEL TANK LID	SCRATCH WITH PAINT DAMAGE
-----	---------------	---------------------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	FRONT BUMPER/CENTER/RIGHT			SCRATCH WITH PAINT DAMAGE		
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

Others

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

1	2	3	4	5	6	7	8	9	10
95.00	115.56	0	0	0	0	0	0	0	0
95.00	115.56	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
210.56	0	0	210.56
HOG: 0	BG: 2		NA Deprec. 210.56
			0.00%
			TOTAL 210.56

APPRAISAL

www.vabfleetservices.be

Date : 22/09/2017

5/5

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min 	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : NAVI OK // OB. + ELECTRONISCH [x]		

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 22/09/2017 Hour : 13:18	
Company : Executed by VAB Fleet Services E-Mail : @	
Signature authorized by customer 	