

www.vabfleetservices.be Date: 25/09/2017 1/5

CQFQQ2

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

Commissionar: **KBC REMARKETING** Cleanliness: INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 105978 KM File nr. : Mileage start / arrival: 1441357 0 / 0Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1FEN692 / WVWZZZAUZDP084503 / E-File nr. : First registration: 07/06/2013 VFS-nr.: Color: **GREY** Make + Model : Fuel type : VOLKSWAGEN / GOLF **DIESEL** Object nr. : Fuel: 43279 **Environment Class:** Classification: EURO 5 Customer company: Co2: BELGACOM INS/FLEET NV 99g/kmDriver : Remote controls: TISSUE Covering: Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): 0 Vehicle type: GOLF BER Trendline 105PK Country registration: **BELGIUM**

Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
нр:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Metallic paint:

Yes



www.vabfleetservices.be Date: 25/09/2017 2/5

Original registr. number :	OK	Service manual :	OK	
Cert. of reg. / Part 1:	OK	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:		Insurance certificate :	OK	
Warning vest:	OK	Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	ОК	
Mobile phone kit :		Extinguisher :	OK	
		Warning triangle :	ОК	
First aid kit :	OK	Oil level :		
Jack, wheelspanner :	OK	Filled up :	0	

Wheels and tyres: Summer tires

Wheel RES:	ANDERE	Tyre:	OK	/	Rim:	/ Hubcap:	
Wheel RR:	MICHELIN	Tyre:	OK	4-6 /	Rim:	/ Hubcap:	SCRATCHED
Wheel FR:	MICHELIN	Tyre:	OK	4-6 /	Rim:	/ Hubcap:	SCRATCHED
Wheel RL:	MICHELIN	Tyre:	OK	4-6 /	Rim:	/ Hubcap:	
Wheel FL:	MICHELIN	Tyre :	OK	4-6 /	Rim:	/ Hubcap:	SCRATCHED

	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	Н
Rear tyre	195	65	R	15	Н

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 25/09/2017 3/5

STATUS: ACCEPTABLE / USAGE DAMAGE

x]	REAR DOOR/LEFT/FRONT		DENT			
	REAR DOOR/LEFT/FRONT		DENI			
[]	FRONT DOOR/LEFT/REAR		SCRATCH WITH PAIN	NT DAMAGE		
κ]	FRONT DOOR/LEFT/CENTER		SCRATCH WITH PAIN	NT DAMAGE		
]	FRONT THRESHOLD/RIGHT/CENTER		DENT		INSTAP	
]	BONNET/CENTER/LEFT		DENT			
]	FRONT BUMPER/LEFT/SIDE		SCRATCH WITH PAIN	NT DAMAGE		
.]	ROOF/CENTER/LEFT		DENT			
ıte	rior					
	BOOT LID IN		CARVED			
CC	essories and others					
	OUTSIDE MIRROR LEFTHAND SIDE		SCRATCH WITH PAIN	NT DAMAGE		
	OUTSIDE MIRROR RIGHTHAND SIDE		SCRATCH (WITHOUT	PAINT DAMAGE)	
ST/	OUTSIDE MIRROR RIGHTHAND SIDE ATUS: NOT ACCEPTAB	LE	SCRATCH (WITHOUT	PAINT DAMAGE)	
		LE	SCRATCH (WITHOUT	PAINT DAMAGE)	
oc	ATUS: NOT ACCEPTAB	LE	SCRATCH (WITHOUT		MEERDERE	
OC	ATUS: NOT ACCEPTAB	LE Repair paint - LI				Total
00	ATUS: NOT ACCEPTAB		SCRATCH WITH PAIN		MEERDERE	
00	ATUS: NOT ACCEPTAB lywork \& windows REAR BUMPER/LEFT/LEFT	Repair paint - LI	SCRATCH WITH PAIN		MEERDERE Depr.	
00	ATUS: NOT ACCEPTAB lywork \& windows REAR BUMPER/LEFT/LEFT 2 0 LU = 0.00 EUR	Repair paint - LI	SCRATCH WITH PAIN New paint - E		MEERDERE Depr.	
	ATUS: NOT ACCEPTAB lywork \& windows REAR BUMPER/LEFT/LEFT 2 0 LU =0.00 EUR REAR MUDGUARD/LEFT/FRONT	Repair paint - LI 211.80 EUR	SCRATCH WITH PAIN New paint - E	NT DAMAGE	MEERDERE Depr. 50 %	211.80 EUF
	ATUS: NOT ACCEPTAB lywork \& windows REAR BUMPER/LEFT/LEFT 2 0 LU =0.00 EUR REAR MUDGUARD/LEFT/FRONT Number Code	Repair paint - LI 211.80 EUR Description	SCRATCH WITH PAIN New paint - E	NT DAMAGE Unit price	MEERDERE Depr. 50 %	211.80 EUF
	ATUS: NOT ACCEPTAB lywork \& windows REAR BUMPER/LEFT/LEFT 2 0 LU = 0.00 EUR REAR MUDGUARD/LEFT/FRONT Number Code I 1 i-vab-sp-01	Repair paint - LI 211.80 EUR Description	SCRATCH WITH PAIN New paint - E DENT	NT DAMAGE Unit price	MEERDERE Depr. 50 % Depr.	211.80 EUF
	ATUS: NOT ACCEPTAB lywork \& windows REAR BUMPER/LEFT/LEFT 2 0 LU =0.00 EUR REAR MUDGUARD/LEFT/FRONT Number Code 1 1 i-vab-sp-01 REAR MUDGUARD/RIGHT/CENTER	Repair paint - LI 211.80 EUR Description SPOTREPAIR	SCRATCH WITH PAIN New paint - E DENT	Unit price	MEERDERE Depr. 50 % Depr. SLECHT HERSTELD	211.80 EUF Total 115.56 EUF
300	ATUS: NOT ACCEPTAB lywork \& windows REAR BUMPER/LEFT/LEFT 2 0 LU =0.00 EUR REAR MUDGUARD/LEFT/FRONT Number Code 1 1 i-vab-sp-01 REAR MUDGUARD/RIGHT/CENTER Number Code	Repair paint - LI 211.80 EUR Description SPOTREPAIR	SCRATCH WITH PAIN New paint - E DENT	Unit price	MEERDERE Depr. 50 % Depr. SLECHT HERSTELD	211.80 EUR Total 115.56 EUR



www.vabfleetservices.be Date: 25/09/2017 4/5

[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE
	TROTT DOOKRIGHT/CETTER	BERGIEL WITH THE DELIVEROE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

1	2	3	4	5	6	7	8	9	10
318.35	211.80	115.56	63.00	0	0	0	0	0	0
159.18	105.90	115.56	63.00	0	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
708.71		0	530.15	178.56
443.64	NA Deprec.		BG: 0	HOG: 0
	0.00%			
443.64	TOTAL			



www.vabfleetservices.be Date: 25/09/2017 5/5

[x] = Status Modification

Pictures: No

CIRCUMSTANCES

CIRCUMSTANCES				NORMAL CONCLUSION				
Extra Time :	0 min	Waiting time: 0 min Reason:			Towing time : Reason :	0 min		
NOT EXECUTED Reason:	O: No	<u> </u>			L			
Remark :								
Prices in EUR	without VAT							
Authorized by customer :				Executed by VAB F	leet Services			
Remark authorize	ed customer :							
Date :	25/09/2017	Hour:	11:25					
Company :								
Executed by VAB Services	Fleet							
E-Mail :	@							
Signature authorize	ed by customer		_					