

www.vabfleetservices.be Date: 19/09/2017 1/5

CNE5SH

[X] EFFECTIVE	[] NOT EXECUTED	[] COLLECTION	[] DELIVERY
---------------	------------------	----------------	--------------

[x] = Status Modification

VAT over the margin - car:

Commissionar :	KBC REMARKETING	Cleanliness:	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	119374 KM
File nr. :	1439036	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HKL140 / JTMZHREV60D0	22618 /	yr of constructionr :	/
E-File nr. :		First registration :	11/08/2014
VFS-nr. :		Color :	SILVER
Make + Model :	TOYOTA / RAV4	Fuel type :	DIESEL
Object nr. :	844509BE300002	Fuel :	
Classification:		Environment Class:	EURO 5
Customer company :	TOYOTA MOTOR EUROPE	Co2:	127g/km
Driver :	DENIS, RONNY	Remote controls:	2
Covering:	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

Variant car:		Engine size:	1998
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
нр:	124	kW:	91
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:		L .	

Metallic paint:

Yes



www.vabfleetservices.be Date: 19/09/2017 2/5

Original registr. number :	OK		Service manual :	NOK	[x] MISSING/INCOMPLETE
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	NOK	[x]	Insurance certificate :		
Warning vest :			Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL: [x] DUNLOP Tyre: OK [x] 2-4/ Rim: / Hubcap: [x] SCRATCHED Wheel RL: [x] DUNLOP Tyre: OK [x] >6/ Rim: / Hubcap: [x] BROKEN/CRACKED Wheel RR: [x] DUNLOP Tyre: OK [x] >6/ Rim: / Hubcap: Wheel RES: [x] Tyre: OK / Rim: / Hubcap: [x] Width Height Type Rim Index		Fron	t tyro		225			65		P		17	П
Wheel RL: [x] DUNLOP Tyre: OK [x] >6/ Rim: / Hubcap: Wheel FR: [x] DUNLOP Tyre: [x] OK [x] 2-4/ Rim: / Hubcap: [x] BROKEN/CRACKED Wheel RR: [x] DUNLOP Tyre: OK [x] >6/ Rim: / Hubcap:	l _			[x]	Width		He	eight		Type		Rim	Index
Wheel RL: [x] DUNLOP Tyre: OK [x] >6/ Rim: / Hubcap: Wheel FR: [x] DUNLOP Tyre: [x] OK [x] 2-4/ Rim: / Hubcap: [x] BROKEN/CRACKED Wheel RR: [x] DUNLOP Tyre: OK [x] >6/ Rim: / Hubcap:	WIII	eei KES.	[X]		Tyre.	OK		,	Killi i		,	пинсар .	
Wheel RL: [x] DUNLOP Tyre: OK [x] >6/ Rim: / Hubcap: / Hubcap: [x] BROKEN/CRACKED	Wha	ool DEC.	[v]		Tyre	OK		/	Dim ·		,	Hubean :	
Wheel RL: [x] DUNLOP Tyre: OK [x] >6/ Rim: / Hubcap:	Whe	eel RR :	[x]	DUNLOF	Tyre:	OK	[x]	>6/	Rim:		/	Hubcap:	
	Whe	eel FR :	[x]	DUNLOF	Tyre: [x	i] OK	[x]	2-4 /	Rim:		/	Hubcap: [x	BROKEN / CRACKED
Wheel FL: [x] DUNLOP Tyre: OK [x] 2-4/ Rim: / Hubcap: [x] SCRATCHED	Who	eel RL:	[x]	DUNLOF	Tyre:	OK	[x]	>6/	Rim:		/	Hubcap:	
	Whe	eel FL:	[x]	DUNLOF	Tyre:	OK	[x]	2-4 /	Rim:		/	Hubcap: [x] SCRATCHED

[x]	Width	Height	Type	Rim	Index
Front tyre	225	65	R	17	Н
Rear tyre	225	65	R	17	Н
		·			<u> </u>

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 19/09/2017 3/5

STATUS: ACCEPTABLE / USAGE DAMAGE

Во	dywork \& windows				
[x]	REAR MUDGUARD/LEFT/CENTER		DENT		
x]	REAR THRESHOLD/LEFT/REAR		SCRATCH WITH PAINT DAMAGE	INT	
x]	REAR DOOR/LEFT/FRONT		DENT	X2	
x]	REAR THRESHOLD/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE	INT	
x]	FRONT THRESHOLD/LEFT/REAR		SCRATCH WITH PAINT DAMAGE	INT	
nte	erior				
[x]	DOOR IN FR		SCRATCHED		
x]	DOOR IN REAR L		SCRATCHED		
x]	BOOT LID IN		SCRATCHED		
Ac	cessories and others				
	OUTSIDE MIRROR ATUS: NOT ACCEPTA	BLE	SCRATCH WITH PAINT DAMAGE		
ST		BLE	SCRATCH WITH PAINT DAMAGE SCRATCH WITH PAINT DAMAGE	MEERDERE	
ST	ATUS: NOT ACCEPTA	BLE Description		MEERDERE Depr.	Total
ST	ATUS: NOT ACCEPTA dywork \& windows REAR BUMPER/CENTER/RIGHT		SCRATCH WITH PAINT DAMAGE		
ST Boo	ATUS: NOT ACCEPTA dywork \& windows REAR BUMPER/CENTER/RIGHT Number Code	Description	SCRATCH WITH PAINT DAMAGE Unit price		
ST Boo	ATUS: NOT ACCEPTA dywork \& windows REAR BUMPER/CENTER/RIGHT Number Code 1 1 i-vab-kunst-01	Description	SCRATCH WITH PAINT DAMAGE Unit price		
Boo(x)	ATUS: NOT ACCEPTA dywork \& windows REAR BUMPER/CENTER/RIGHT Number Code 2 I 1 i-vab-kunst-01	Description	SCRATCH WITH PAINT DAMAGE Unit price 110.64 EUR		
Boo(x)	ATUS: NOT ACCEPTA dywork \& windows REAR BUMPER/CENTER/RIGHT Number Code 2 I 1 i-vab-kunst-01 Prior CARPET FR	Description PLASTICS REPAIR	SCRATCH WITH PAINT DAMAGE Unit price 110.64 EUR STAIN	Depr.	110.64 EUF
ST Boo	ATUS: NOT ACCEPTA dywork \& windows REAR BUMPER/CENTER/RIGHT Number Code 2 I 1 i-vab-kunst-01 Prior CARPET FR Number Code	Description PLASTICS REPAIR Description	SCRATCH WITH PAINT DAMAGE Unit price 110.64 EUR STAIN Unit price	Depr.	110.64 EUF
ST Boo	ATUS: NOT ACCEPTA dywork \& windows REAR BUMPER/CENTER/RIGHT Number Code 2 I 1 i-vab-kunst-01 Prior CARPET FR Number Code 1 I 1 i-vab-rein-07	Description PLASTICS REPAIR Description	SCRATCH WITH PAINT DAMAGE Unit price 110.64 EUR STAIN Unit price 14.58 EUR	Depr.	110.64 EUF
ST Boo	ATUS: NOT ACCEPTA dywork \& windows REAR BUMPER/CENTER/RIGHT Number Code 2 I 1 i-vab-kunst-01 Prior CARPET FR Number Code 1 I 1 i-vab-rein-07 SEAT FR	Description PLASTICS REPAIR Description CLEANING (PER 15')	SCRATCH WITH PAINT DAMAGE Unit price 110.64 EUR STAIN Unit price 14.58 EUR STAIN	Depr. Depr.	Total 14.58 EUR
ST Boo [x]	ATUS: NOT ACCEPTA dywork \& windows REAR BUMPER/CENTER/RIGHT Number Code 2 I 1 i-vab-kunst-01 Prior CARPET FR Number Code 1 I 1 i-vab-rein-07 SEAT FR Number Code	Description PLASTICS REPAIR Description CLEANING (PER 15') Description	SCRATCH WITH PAINT DAMAGE Unit price 110.64 EUR STAIN Unit price 14.58 EUR STAIN Unit price	Depr. Depr.	Total 14.58 EUR
Bo ([x]	ATUS: NOT ACCEPTA dywork \& windows REAR BUMPER/CENTER/RIGHT Number Code 2 I 1 i-vab-kunst-01 Prior CARPET FR Number Code 1 I 1 i-vab-rein-07 SEAT FR Number Code 1 I 1 i-vab-rein-07	Description PLASTICS REPAIR Description CLEANING (PER 15') Description	SCRATCH WITH PAINT DAMAGE Unit price 110.64 EUR STAIN Unit price 14.58 EUR 14.58 EUR	Depr. Depr.	110.64 EUR Total 14.58 EUR



www.vabfleetservices.be Date: 19/09/2017 4/5

Others

HUB CAP FR

Repair paint - LI New paint - E Depr. Total

3 0 LU =0.00 EUR 50 %

Pieces

1	Number	Code	Description	Unit price	Depr.	Total
3	1	WHEEL CAP		30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
43.74	110.64	30.00	0	0	0	0	0	0	0
43.74	110.64	15.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
154.38	30.00	0		184.38
HOG: 0	BG: 0		NA Deprec.	169.38

0.00% TOTAL 169.38



5/5

19/09/2017 www.vabfleetservices.be Date: [x] = Status Modification **Pictures:** No **CIRCUMSTANCES** NORMAL CONCLUSION Extra Time : $0 \min$ Waiting time: 0 min Towing time : $0 \min$ Reason: Reason: NOT EXECUTED: No Reason: Remark: Prices in EUR without VAT Authorized by Executed by VAB Fleet Services customer : Remark authorized customer : Date : 19/09/2017 Hour: 10:31 Company: Executed by VAB Fleet Services E-Mail: Signature authorized by customer