

www.vabfleetservices.be Date: 03/10/2017 1/5

CR9D3G

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 114924 KM File nr. : Mileage start / arrival: 0 / 01442010 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1FBZ754 / WDD2122051A801949 / E-File nr. : First registration: 21/05/2013 Color: VFS-nr.: **GOLD** Make + Model : Fuel type : MERCEDES / E BREAK **DIESEL** Object nr. : Fuel: Classification: **Environment Class:** EURO 5 Customer company: Co2: BELGACOM INS/FLEET NV 135g/km Driver : Remote controls: 2 TISSUE Covering: Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): 0 Vehicle type: E BRE 200CDI BE Start/Stop 136PK Country registration: **BELGIUM**

Variant car:	BREAK	Engine size:	2143
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:	_	ı	

Metallic paint:

Yes



www.vabfleetservices.be Date: 03/10/2017 2/5

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:	OK	Cert. of conformity:	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	OK
Warning vest :	OK	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	ОК
Mobile phone kit :		Extinguisher :	OK
		Warning triangle :	OK
First aid kit :	OK	Oil level :	ОК
Jack, wheelspanner :	OK	Filled up :	0

Wheels and tyres: Summer tires

Fr	ont tyre	[x]	Width 225			eight 55			Type R		Rim 16	Index W
Wheel RES	: [x]	AND		OK		/	Rim:				/ Hubcap :	
Wheel RR:		AND	·	OK	[x]	4-6 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel FR:	[x]	MICI	HELIN Tyre:	OK		2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel RL:	[x]	AND	ERE Tyre:	OK	[x]	4-6 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel FL:	[x]	MICI	HELIN Tyre:	OK		2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap :	

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



SEAT REAR RIGHT

i-vab-rein-07

Number Code

I 1

[x]

APPRAISAL

www.vabfleetservices.be Date: 03/10/2017 3/5

STATUS: ACCEPTABLE / USAGE DAMAGE

_							
Во	dywork \& windows						
[x]	REAR MUDGUARD/LEFT/REAR		DENT				
[x]	REAR MUDGUARD/RIGHT/FRONT		SCRATCH (WITHOUT PAINT DAMAGE)	POL			
[x]	REAR DOOR/RIGHT/CENTER		SCRATCH (WITHOUT PAINT DAMAGE)	POL			
[x]	REAR THRESHOLD/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE	INSTAP			
x]	FRONT DOOR/LEFT/REAR		SCRATCH WITH PAINT DAMAGE	DEURRAND + DEUK			
x]	ROOF STYLE/FRONT/LEFT/CENTER		CHIPS				
x]	FRONT DOOR/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE	RAND			
x]	FRONT BUMPER/RIGHT		SCRATCH WITH PAINT DAMAGE				
			SCRATCH WITH PAINT DAMAGE				
[x]	FRONT BUMPER/RIGHT/SIDE		SCRATCH WITH PAINT DAMAGE				
	FRONT BUMPER/RIGHT/SIDE ATUS: NOT ACCEPTAB	LE	SCRATCH WITH PAINT DAMAGE				
ST		LE	SCRATCH WITH PAINT DAMAGE				
ST	ATUS: NOT ACCEPTAB	LE	SCRATCH WITH PAINT DAMAGE SCRATCH WITH PAINT DAMAGE	MEERDERE			
ST	ATUS: NOT ACCEPTAB	LE Repair paint - LI		MEERDERE Depr.	Total		
ST	ATUS: NOT ACCEPTAB		SCRATCH WITH PAINT DAMAGE				
ST Bo	ATUS: NOT ACCEPTAB dywork \& windows REAR BUMPER/LEFT/LEFT	Repair paint - LI	SCRATCH WITH PAINT DAMAGE	Depr.			
ST Bo	ATUS: NOT ACCEPTAB dywork \& windows REAR BUMPER/LEFT/LEFT 2 0 LU =0.00 EUR	Repair paint - LI	SCRATCH WITH PAINT DAMAGE	Depr.			
ST Bo	ATUS: NOT ACCEPTAB dywork \& windows REAR BUMPER/LEFT/LEFT 2 0 LU =0.00 EUR	Repair paint - LI	SCRATCH WITH PAINT DAMAGE New paint - E	Depr.			
ST Bo	ATUS: NOT ACCEPTAB dywork \& windows REAR BUMPER/LEFT/LEFT 2 0 LU =0.00 EUR erior SEAT FL	Repair paint - LI 254.16 EUR	SCRATCH WITH PAINT DAMAGE New paint - E STAIN	Depr. 50 %	254.16 EUI		
ST Bo	ATUS: NOT ACCEPTAB dywork \& windows REAR BUMPER/LEFT/LEFT 2 0 LU =0.00 EUR Prior SEAT FL Number Code	Repair paint - LI 254.16 EUR Description	SCRATCH WITH PAINT DAMAGE New paint - E STAIN Unit price	Depr. 50 %	254.16 EUI		
Bo	ATUS: NOT ACCEPTAB dywork \& windows REAR BUMPER/LEFT/LEFT 2 0 LU =0.00 EUR Prior SEAT FL Number Code 1 I 1 i-vab-rein-07	Repair paint - LI 254.16 EUR Description	SCRATCH WITH PAINT DAMAGE New paint - E STAIN Unit price 14.58 EUR	Depr. 50 %	254.16 EUF		

STAIN

Unit price

14.58 EUR

Depr.

Total

14.58 EUR

Description

CLEANING (PER 15')



www.vabfleetservices.be Date: 03/10/2017 4/5

1	2	3	4	5	6	7	8	9	10
43.74	254.16	0	0	0	0	0	0	0	0
43.74	127.08	0	0	0	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
297.90		0	254.16	43.74
170.82	NA Deprec.		BG: 2	HOG: 0
	0.00%			
170.82	TOTAL			



www.vabfleetservices.be Date: 03/10/2017 5/5

[x] = Status Modification

Pictures: No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time :	0 min	Waiting t	time: 0 min	n	Towing time :	0 min	
		Reason:	Reason:		Reason:		
NOT EXECUTED:	No						
Reason:							
Remark:	NAVI OK						
Prices in EUR wi	ithout VAT						
Authorized by customer :				Executed by VAB Fle	et Services		
Remark authorized c	ustomer :						
Date :	03/10/2017	Hour:	09:49				
Company:							
Executed by VAB Flo Services	eet						
E-Mail :							
Signature authorized b	v customer						
×	y customer						
-							