

Environment Class:

www.vabfleetservices.be Date: 12/10/2017 1/4

CWVYKN

[X] EFFECTIVE [] NOT EXECUTED [] COLLECTION [] DELIVERY

[x] = Status Modification

Classification:

Commissionar: KBC REMARKETING Cleanliness: INT: CLEAN [x] EXT: CLEAN [x]

Owner: Mileage: 159860 KM

File nr.: 1446399 Mileage start / arrival: 0 / 0

Reg number / Chassis / Ref:

Mileag ref. service:

O

YF5509 / WVWZZZ7NZEV008203 /

yr of constructionr: /

E-File nr.: First registration: 24/09/2013

VFS-nr.: Color: GREY

Make + Model : VOLKSWAGEN / SHARAN Fuel type : DIESEL

Wake + Woder: VOLKSWAGEN / SHARAN Fuel type: DIESEL

Object nr.: Fuel:

Customer company: Fujitsu Technology Solutions Co2: g/km

Driver: Remote controls: 2

Covering:LEATHERNumber keys:2 [x]Vehicle kind:VEHICLESeats (minivan):7 [x]

Vehicle type: SHARAN Highline BMT St/St 177PK Country registration: LUXEMBOURG

VAT over the margin - car: No Metallic paint: Yes

Variant car: MONOVOLUME Engine size: 1968

Gear box: Manueel Number of places: 7

Number of gears: 6 Number of doors: 5

HP: 177 **kW:** 130

Fisc HP Imported vehicle: No

Animals transported: No Smoked in vehicle: No

Due date vehicle inspection: Extra set of tires: No

Use: Unknown

General condition:



www.vabfleetservices.be Date: 12/10/2017 2/4

Original registr. number :			Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity :		
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICI	HELIN	Tyre:		OK	[x]	2-4 /	Rim:				/ Hubcap :	
Wheel RL:	[x]	MICI	HELIN	Tyre:		OK	[x]	4-6 /	Rim:				/ Hubcap :	
Wheel FR:	[x]	MICI	HELIN	Tyre:	[x]	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap :	
Wheel RR:	[x]	MICI	HELIN	Tyre:		OK	[x]	4-6 /	Rim:				/ Hubcap :	
Wheel RES:	[x]			Tyre:		OK		/	Rim:				/ Hubcap:	
		[x]		Width			Н	eight			Type		Rim	Index
Fron	t tyre			225				50			R		17	Y
Rear	tyre			225				50			R		17	Y

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:

Remark:



www.vabfleetservices.be Date: 12/10/2017 3/4

STATUS: NOT ACCEPTABLE

Bodywork \& windows								
[x] REAR BUMPER/CEN	TER/LEFT	SCRATCH WITH PAINT DAMAGE	MEERDERE					
	Repair paint - LI	New paint - E	Depr.	Total				
2 0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR				
Othors								

Others

RIM FRONT RIGHT

]	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

	1	2	3	4	5	6	7	8	9	10
	95.00	254.16	0	0	0	0	0	0	0	0
ĺ	95.00	127.08	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
95.00	254.16	0		349.16
HOG: 0	BG: 2		NA Deprec.	222.08
			0.00%	
			TOTAL	222.08



www.vabfleetservices.be Date: 12/10/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMS		NORMAL CONCLUSION						
Extra Time :	0 min	Waiting time: 0 Reason:) min	Towing time : Reason :	0 min			
NOT EXECUTED Reason:	No No							
Remark :								
Prices in EUR	without VAT							
Authorized by customer:			Executed by VA	B Fleet Services				
Remark authorized	d customer :							
Date :	12/10/2017	Hour: 08:30						
Company:								
Executed by VAB Services	Fleet							
E-Mail :	@							
Signature authorized	d by customer							