

CU6FTR

☒ EFFECTIVE
 ☐ NOT EXECUTED
 ☒ COLLECTION
 ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	159167 KM
File nr. :	1444323	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FDU758 / YV1DZ31A1D2467960 /		yr of constructionr :	/
E-File nr. :		First registration :	03/06/2013
VFS-nr. :		Color :	BLACK
Make + Model :	VOLVO / XC60	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	MEDIAFIN NV	Co2:	139g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	XC60 D3 Kinetic Start/Stop 136PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	
Variant car:	SUV	Engine size:	1984
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:	
--------------------	--

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
			Warning triangle :	OK [x]
First aid kit :	OK	[x]	Oil level :	OK [x]
Jack, wheelspanner :			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :		/	Hubcap :
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED / Hubcap :
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	235	65	R	17	H
Rear tyre	235	65	R	17	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/RIGHT/RIGHT	SCRATCH WITH PAINT DAMAGE
[x]	REAR MUDGUARD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT DOOR/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	BONNET/CENTER/RIGHT	SCRATCH (WITHOUT PAINT DAMAGE)

Interior

[x]	DOOR IN FL	CARVED
[x]	DOOR IN FR	CARVED
[x]	DOOR IN REAR RIGHT	CARVED
[x]	BOOT IN L	CARVED

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT			SCRATCH WITH PAINT DAMAGE		
			Repair paint - LI	New paint - E	Depr.	Total
6	0 LU =0.00 EUR		211.80 EUR		50 %	211.80 EUR
[x]	REAR MUDGUARD/LEFT/FRONT			DENT		
	Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	REAR WINDOW/LEFT			WINDOW DAMAGE		
			Repair paint - LI	New paint - E	Depr.	Total
7	0 LU =0.00 EUR		0 EUR		50 %	
			Repair paint - LI	New paint - E	Depr.	Total
7	25 LU =120.00 EUR		0 EUR		50 %	120.00 EUR

[x]	REAR MUDGUARD/RIGHT/FRONT		DENT		
			Repair paint - LI	New paint - E	Depr.
					Total
8	15 LU =72.00 EUR		308.20 EUR		50 %
					380.20 EUR
[x]	REAR DOOR/LEFT/FRONT		DENT		
			Repair paint - LI	New paint - E	Depr.
					Total
4	10 LU =48.00 EUR		318.35 EUR		50 %
					366.35 EUR
[x]	ROOF/REAR/RIGHT		DENT		
	Number	Code	Description	Unit price	Depr.
					Total
10	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR	
					63.00 EUR
[x]	FRONT DOOR/RIGHT/FRONT		DENT		
	Number	Code	Description	Unit price	Depr.
					Total
9	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR	
					63.00 EUR
[x]	FRONT MUDGUARD/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE		
			Repair paint - LI	New paint - E	Depr.
					Total
10	0 LU =0.00 EUR		220.18 EUR		50 %
					220.18 EUR
[x]	FRONT BUMPER/RIGHT/SIDE		SCRATCH WITH PAINT DAMAGE		
			Repair paint - LI	New paint - E	Depr.
					Total
3	0 LU =0.00 EUR		211.80 EUR		50 %
					211.80 EUR

Interior

[x]	DOOR IN REAR L		CARVED		
			Repair paint - LI	New paint - E	Depr.
					Total
1	5 LU =24.00 EUR		0 EUR		50 %
					24.00 EUR
[x]	BOOT IN R		CARVED		
			Repair paint - LI	New paint - E	Depr.
					Total
1	5 LU =24.00 EUR		0 EUR		50 %
					24.00 EUR

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE		BROKEN / CRACKED		
			Repair paint - LI	New paint - E	Depr.
					Total
2	5 LU =24.00 EUR		0 EUR		50 %
					24.00 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 4	personenwagen-a-vab-rein-02	CLEANING INTERIOR	11.47 EUR	45.88 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	UPHOLSTERY DOOR	90.00 EUR	50 %	90.00 EUR
Number	Code	Description	Unit price	Depr.	Total
1	1	UPHOLSTERY DOOR	90.00 EUR	50 %	90.00 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	MIRROR	120.00 EUR	50 %	120.00 EUR
Number	Code	Description	Unit price	Depr.	Total
7	1	BACK WINDOW	250.00 EUR	50 %	250.00 EUR

1	2	3	4	5	6	7	8	9	10
273.88	144.00	211.80	366.35	63.00	211.80	370.00	380.20	63.00	283.18
159.88	72.00	105.90	183.18	63.00	105.90	185.00	190.10	63.00	173.09

INNOVATIVE	TRADITIONAL	GENERAL	
234.88	2132.33	0	2367.21
HOG: 0	BG: 0		NA Deprec. 1301.04
			0.00%
			TOTAL 1301.04

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 04/10/2017 Hour : 09:19	
Company : Executed by VAB Fleet Services E-Mail : @	
Signature authorized by customer 	