

www.vabfleetservices.be Date: 17/10/2017 1/4

CZAOW8

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: DIRTY [x] Owner: Mileage : 118617 KM File nr. : Mileage start / arrival: 0 / 01448248 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1FPM493 / WBA1C91040J516531 / E-File nr. : First registration: 16/09/2013 Color: VFS-nr.: **BROWN D** Make + Model : Fuel type : BMW / 1 **DIESEL** Object nr. : Fuel: 705174 Classification: **Environment Class:** EURO 5 Customer company: Co2: NGDATA EUROPE BVBA 99g/kmDriver : Remote controls: 2 IMITATION LEATHER Covering: Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): 0 Vehicle type: 1 HATCH 116d Eff.Dyn.Ed. 116PK Country registration: **BELGIUM**

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:		1	



www.vabfleetservices.be Date: 17/10/2017 2/4

Original registr. number :	OK		Service manual :		
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	D	/ Hubcap:		
Wheel RL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:		
Wheel FR:	[x]	MICHELIN	Tyre:	[x]	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:		
Wheel RR:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:		
Wheel RES:	[x]		Tyre:		OK		/	Rim:				/ Hubcap:		
														_
		[x]	Width			He	eight			Type		Rim	Index]
From	it tyre		205	-T			55			P		16	н	1

 [x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	Н
Rear tyre	205	55	R	16	Н

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

 [x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 17/10/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

[X] REAR DOOR/RIGHT/REAR SCRATCH WITH PAINT DAMAGE

[x] FRONT DOOR/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

BONNET/CENTER/LEFT		DENT		MET LAKSCH	ADE
	Repair paint - LI	New paint - E		Depr.	Total
1 0 LU =0.00 EUR	290.08 EUR			50 %	290.08 EUR
hers					
RIM REAR RIGHT					
Number Code	Description		Unit price	Depr.	Total
2 I 1 i-vab-herstalu-02	REPAIR ALLOY WH	EEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT				
Number Code	Description	Unit price	Depr.	Total

2 I 1 i-vab-herstalu-02 REPAIR ALLOY WHEEL 95.00 EUR 95.00 EUR

1	2	3	4	5	6	7	8	9	10
290.08	190.00	0	0	0	0	0	0	0	0
145.04	190.00	0	0	0	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
480.08		0	290.08	190.00
335.04	NA Deprec.		BG: 0	HOG: 0
	0.00%			
335.04	TOTAL			



www.vabfleetservices.be Date: 17/10/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMST	ANCES								
CIRCUMSI	ANCES		NORMAL CONCLUSION						
Extra Time :	0 min	Waiting time: 0 min Reason:	n	Towing time : Reason :	0 min				
NOT EXECUTED : Reason :	No	_		l					
Remark:									
Prices in EUR wit	thout VAT								
Authorized by customer :			Executed by VAB Fleet Se	ervices					
Remark authorized cu	stomer :								
Date : Company :	17/10/2017	Hour: 16:19							
Executed by VAB Flee Services	et								
E-Mail :	@								
Signature authorized by	customer								