

www.vabfleetservices.be Date: 17/10/2017 1/4

D10I3Y

## [X] EFFECTIVE [ ] NOT EXECUTED [X] COLLECTION [ ] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner:		Mileage :	172898 KM
File nr. :	1449605	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GCV155 / VF73A9HC8DJ84	8089 /	yr of constructionr :	/
E-File nr. :		First registration :	03/01/2014
VFS-nr. :		Color :	GREY
Make + Model :	CITROEN / C4 PICASSO	Fuel type :	DIESEL
Object nr. :	70124	Fuel:	
Classification:		Environment Class:	EURO 5
Customer company :	Uitgeverij Lannoo nv	Co2:	105g/km
Driver :		Remote controls:	2
Covering:	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	7 [x]
Vehicle type :	GR.C4 PICASSO Business GPS 115PK	Country registration :	BELGIUM

		1	
Variant car:	MONOVOLUME	Engine size:	1560
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
нр:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:	_	<u> </u>	

Metallic paint:

Yes



www.vabfleetservices.be Date: 17/10/2017 2/4

Original registr. number: OK Service manual: OK [x]

Cert. of reg. / Part 1: OK [x]

Cert. of conformity: OK

Cert. of reg. copy / Part 2: Insurance certificate :
Warning vest : Transport licence :

Warning vest : Transport licence :

Tax certificate : Navigation CD/SD/DVD

Fuel card: Car radio: OK [x]

Mobile phone kit : Extinguisher :

Warning triangle: OK [x]

First aid kit:

Oil level:

OK [x]

Jack, wheelspanner: OK [x] Filled up: 0

### Wheels and tyres: Summer tires

Wheel FL:	[x]	KLÉBER	Tyre:		OK	[x]	4-6/	Rim:	[x]	WHEEL SCRATCHED	/	Hubcap:
Wheel RL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	/	Hubcap:
Wheel FR:	[x]	KLÉBER	Tyre:	[x]	OK	[x]	4-6 /	Rim:	[x]	WHEEL SCRATCHED	/	Hubcap:
Wheel RR:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	/	Hubcap:
Wheel RES:	[x]	KLÉBER	Tvre:		OK	[x]	>6 /	Rim:			/	Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	205	60	R	16	Н
Rear tyre	205	60	R	16	Н

Remark:

### Wheels and tyres:

1						
	Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
	Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
	Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
	Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
	Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 17/10/2017 3/4

### STATUS: ACCEPTABLE / USAGE DAMAGE

[x] REAR MUDGUARD/RIGHT/REAR

DENT

#### STATUS: NOT ACCEPTABLE

REAR DOOR/RIGHT/CENTER		SCRATCH WITH PAINT DAMAGE	VANDALISME	
	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUF
FRONT DOOR/RIGHT/CENTER		SCRATCH WITH PAINT DAMAGE	VANDALISME	
	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUI
FRONT BUMPER/RIGHT		SCRATCH WITH PAINT DAMAGE		
	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUI

#### Others

RIM FRONT LEFT

1	Number	Code	Description	Unit price	Depr.	Total
3	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
211.80	636.70	95.00	0	0	0	0	0	0	0
105.90	318.35	95.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
95.00	848.50	0		943.50
HOG: 0	BG: 0		NA Deprec.	519.25

0.00%
TOTAL 519.25



www.vabfleetservices.be Date: 17/10/2017 4/4

[x] = Status Modification

**Pictures:** No

**CIRCUMSTANCES** 

UNDER CONDITION - DUSTY VEHICLE

	31111(02)5			UNDER CON	DITION - DUSTY VEHICLE		
Extra Time :	0 min	Waiting t	ime: 0 min	1	Towing time :	0 min	
		Reason:			Reason:		
NOT EXECUTED	); No						
Reason:							
Remark:							
Prices in EUR	without VAT						
Authorized by customer :				Executed by VAB F	Fleet Services		
Remark authorize	ed customer :						
Date :	17/10/2017	Hour :	15:33				
Company:							
Executed by VAB Services	Fleet						
E-Mail :	@						
Signature authorize	ed by customer						
_			•				
	<u> </u>						