

www.vabfleetservices.be Date: 16/10/2017 1/5

CW87XF

# [X] EFFECTIVE [ ] NOT EXECUTED

No

[X] COLLECTION

[ ] DELIVERY

[x] = Status Modification

VAT over the margin - car:

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner:		Mileage :	93618 KM
File nr. :	1445893	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref:		Mileag ref. service :	0
1FJN825 / WDD2042021G	168119 /	yr of constructionr :	/
E-File nr. :		First registration :	17/07/2013
VFS-nr.:		Color :	GREY
Make + Model :	MERCEDES / C BREAK	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification:		Environment Class:	EURO 5
Customer company:	BELGACOM INS/FLEET NV	Co2:	114g/km
Driver:		Remote controls:	1
Covering:	PARTIAL LEATHER	Number keys :	1 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :	C BRE 220CDI BE Edition Avantgarde 163PK	Country registration :	BELGIUM

		1	
Variant car:	BREAK	Engine size:	2143
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	163	kW:	120
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:		I	

Metallic paint:

Yes



www.vabfleetservices.be Date: 16/10/2017 2/5

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :		
Jack, wheelspanner :	OK	[x]	Filled up :	0	

## Wheels and tyres: Summer tires

Wheel FL:	[x]	HAN	NGKOOK	Tyre:		OK	[x]	4-6 /	Rim:				/ Hubcap:	
Wheel RL:	[x]	HAN	NGKOOK	Tyre:		OK	[x]	4-6 /	Rim:				/ Hubcap:	
Wheel FR:	[x]	HAN	NGKOOK	Tyre:	[x]	OK	[x]	4-6 /	Rim:				/ Hubcap:	
Wheel RR:	[x]	HAN	NGKOOK	Tyre:		OK	[x]	4-6 /	Rim:	[x]	WHEEL SCRATCHED	)	/ Hubcap:	
Wheel RES:	[x]	ANE	DERE	Tyre:		OK		/	Rim:				/ Hubcap:	
		[x]		Width			Н	eight	İ		Туре		Rim	Index
Fron	ıt tyre			205				55			R		16	V
Rea	r tyre			205				55			R		16	V

Remark:

### Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

 [x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



16/10/2017 Date: www.vabfleetservices.be 3/5

T	ATUS: ACCEPTABLE / US				
00	dywork \& windows				
]	REAR BUMPER/LEFT/CORNER		SCRATCH WITH PAINT DAMAGE		
]	FRONT DOOR/LEFT/REAR		SCRATCH WITH PAINT DAMAGE	RAND	
]	FRONT DOOR/RIGHT/REAR		DENT	2X	
]	FRONT DOOR/RIGHT/CENTER		SCRATCH WITH PAINT DAMAGE		
]	FRONT MUDGUARD/LEFT/CENTER		SCRATCH WITH PAINT DAMAGE		
ιt€	erior				
ı T	SEAT REAR RIGHT  ATUS: NOT ACCEPTABL	E	STAIN		
T		E	STAIN		
T	ATUS: NOT ACCEPTABL	E	SCRATCH (WITHOUT PAINT DAMAGE)	MEERDERE POL	
T	ATUS: NOT ACCEPTABL	<b>E</b> Description		MEERDERE POL  Depr.	Total
T	ATUS: NOT ACCEPTABL  dywork \& windows  REAR DOOR/LEFT/FRONT		SCRATCH (WITHOUT PAINT DAMAGE)		Total
T	ATUS: NOT ACCEPTABL  dywork \& windows  REAR DOOR/LEFT/FRONT  Number Code		SCRATCH (WITHOUT PAINT DAMAGE)		Total
800	ATUS: NOT ACCEPTABL  dywork \& windows  REAR DOOR/LEFT/FRONT  Number Code  0 0		SCRATCH (WITHOUT PAINT DAMAGE)  Unit price		Total
5 <b>T</b>	ATUS: NOT ACCEPTABL  dywork \& windows  REAR DOOR/LEFT/FRONT  Number Code  0 0	Description	SCRATCH (WITHOUT PAINT DAMAGE)  Unit price  SCRATCH WITH PAINT DAMAGE	Depr.	
300 301	ATUS: NOT ACCEPTABL  dywork \& windows  REAR DOOR/LEFT/FRONT  Number Code  0 0  FRONT BUMPER/RIGHT/SIDE	Description  Repair paint - LI	SCRATCH (WITHOUT PAINT DAMAGE)  Unit price  SCRATCH WITH PAINT DAMAGE	Depr. Depr.	Total
300 301	ATUS: NOT ACCEPTABL  dywork \& windows  REAR DOOR/LEFT/FRONT  Number Code  0 0  FRONT BUMPER/RIGHT/SIDE  2 0 LU = 0.00 EUR	Description  Repair paint - LI	SCRATCH (WITHOUT PAINT DAMAGE)  Unit price  SCRATCH WITH PAINT DAMAGE	Depr. Depr.	Total
300 301	ATUS: NOT ACCEPTABL  dywork \& windows  REAR DOOR/LEFT/FRONT  Number Code  0 0  FRONT BUMPER/RIGHT/SIDE  2 0 LU = 0.00 EUR	Description  Repair paint - LI	SCRATCH (WITHOUT PAINT DAMAGE)  Unit price  SCRATCH WITH PAINT DAMAGE	Depr. Depr.	Total

1	2	3	4	5	6	7	8	9	10
29.16	211.80	0	0	0	0	0	0	0	0
29.16	105.90	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
29.16	211.80	0		240.96
HOG: 0	BG: 0		NA Deprec.	135.06
			0.00%	

TOTAL 135.06



www.vabfleetservices.be Date: 16/10/2017 4/5



www.vabfleetservices.be Date: 16/10/2017 5/5

[x] = Status Modification

Pictures: No

**CIRCUMSTANCES** 

UNDER CONDITION - DUSTY VEHICLE

Extra Time :	0 min	Waiting time:	0 min		Towing time :	0 min
		Reason:			Reason:	
NOT EXECUTED :	No	<u> </u>				
Reason:						
Remark:						
Prices in EUR with	out VAT					
Authorized by customer :				Executed by VAB Fleet Se	rvices	
customer .						
Remark authorized cust	omer :					
Date :	16/10/2017 H	<b>Iour:</b> 11:33				
Company:						
Executed by VAB Fleet Services						
E-Mail :	@					
Signature authorized by c	ustomer					
×						