

D07F46

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	88125 KM
File nr. :	1448968	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HCL995 / WAUZZZ8VXEA184007 /		yr of constructionr :	/
E-File nr. :		First registration :	18/06/2014
VFS-nr. :		Color :	GREY
Make + Model :	AUDI / A3 SPORTBACK	Fuel type :	DIESEL
Object nr. :	713108	Fuel :	
Classification :	E	Environment Class:	EURO 5
Customer company :	PWC BUSINESS SERVICES CVBA	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:	OK	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :		Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
		Warning triangle :	OK
First aid kit :	OK	Oil level :	OK
Jack, wheelspanner :		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	CONTINENTAL	Tyre :	OK	4-6 /	Rim :	/	Hubcap :
Wheel RL :	CONTINENTAL	Tyre :	OK	4-6 /	Rim :	/	Hubcap :
Wheel FR :	CONTINENTAL	Tyre :	OK	4-6 /	Rim :	WHEEL SCRATCHED	Hubcap :
Wheel RR :	CONTINENTAL	Tyre :	OK	4-6 /	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	W
Rear tyre	205	55	R	16	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/LEFT/FRONT	DENT		
[x]	ROOF/CENTER/LEFT	OTHER DAMAGES	POLIEREN	

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT			DENT		
			Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR		169.44 EUR		50 %	169.44 EUR
[x]	FRONT MUDGUARD/LEFT/FRONT			SCRATCH WITH PAINT DAMAGE		
	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR
[x]	BONNET/CENTER/LEFT			OTHER DAMAGES		CHEMISCHE INWERKING
			Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR		232.06 EUR		50 %	232.06 EUR
[x]	FRONT BUMPER/LEFT/SIDE			SCRATCH WITH PAINT DAMAGE		
			Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR		169.44 EUR		50 %	169.44 EUR

Others

RIM FRONT RIGHT

	Number Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
285.00	169.44	232.06	95.00	0	0	0	0	0	0
200.28	84.72	116.03	95.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
210.56	570.94	0	781.50
HOG: 0	BG: 1		NA Deprec. 496.03
			0.00%
			TOTAL 496.03

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : NAVI OK		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 20/10/2017 Hour : 11:21 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	