

www.vabfleetservices.be Date: 20/10/2017 1/4

D10ZDH

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

General condition:

Commissionar: **KBC REMARKETING** Cleanliness: INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 180886 KM File nr. : Mileage start / arrival: 1450122 0 / 0Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1DKU524 / WF0JXXWPBJCA63040 /

E-File nr.: 12/06/2012
VFS-nr.: Color: BLUE D

Make + Model : FORD / C-MAX Fuel type : DIESEL

Object nr.: 12055 Fuel:

Classification: Environment Class: EURO 5

Customer company: ERICSSON N.V./S.A. Co2: 114g/km

Driver: Remote controls: 2

Covering: LEATHER Number keys: 2[x] Vehicle kind: VEHICLE Seats (minivan): 0

 Vehicle type :
 C-MAX Titanium St/St 95PK
 Country registration :
 BELGIUM

Metallic paint: VAT over the margin - car: No Yes 1560 Variant car: Engine size: Gear box : Number of places: 5 Manueel Number of gears: 6 Number of doors: 5 HP: 95 kW: 70 Fisc HP Imported vehicle: Animals transported: No Smoked in vehicle: No Due date vehicle inspection: Extra set of tires: No Use: Unknown



www.vabfleetservices.be Date: 20/10/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest:	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	BRIDGESTONE	Tyre:		OK	[x]	2-4 /	Rim :	/ Hubcap:
Wheel RL:	[x]	BRIDGESTONE	Tyre:		OK	[x]	2-4 /	Rim:	/ Hubcap:
Wheel FR:	[x]	BRIDGESTONE	Tyre:	[x]	OK	[x]	2-4 /	Rim:	/ Hubcap:
Wheel RR:	[x]	BRIDGESTONE	Tyre:		OK	[x]	2-4 /	Rim:	/ Hubcap:
Wheel RES:	[x]		Tyre:		OK		/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	215	55	R	16	Н
Rear tyre	215	55	R	16	Н

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

 [x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 20/10/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

[x] FRONT BUMPER/RIGHT SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR WINDOW/LEFT SCRATCH WITH PAINT DAMAGE

 Repair paint - LI
 New paint - E
 Depr.
 Total

 1 25 LU = 120.00 EUR
 0 EUR
 50 %
 120.00 EUR

Pieces

ľ	Number	Code	Description	Unit price	Depr.	Total
1	1	BACK WINDOW		250.00 EUR	50 %	250.00 EUR

1	2	3	4	5	6	7	8	9	10
370.00	0	0	0	0	0	0	0	0	0
185.00	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
0	370.00	0		370.00
HOG: 0	BG: 0		NA Deprec.	185.00
			0.00%	

0.00%
TOTAL 185.00



www.vabfleetservices.be Date: 20/10/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMSTANCES			NORMAL CONCLUSION					
Extra Time :	0 min	Waiting time : 0 m Reason :	nin	Towing time : Reason :	0 min			
NOT EXECUTED Reason:	: No	<u> </u>		<u> </u>				
Remark :								
Prices in EUR	without VAT							
Authorized by customer :			Executed by VAB I	Fleet Services				
Remark authorized	l customer :							
Date :	20/10/2017	Hour: 12:40						
Company : Executed by VAB I Services	Fleet							
E-Mail:	@							
Signature authorized	l by customer							