

www.vabfleetservices.be Date: 25/10/2017 1/4

D2YCBM

### [X] EFFECTIVE [ ] NOT EXECUTED [X] COLLECTION [ ] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	112959 KM
File nr. :	1451154	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1ESU282 / WF0JXXWPBJCT	62688 /	yr of constructionr :	/
E-File nr. :		First registration :	12/03/2013
VFS-nr. :		Color :	GREY
Make + Model :	FORD / C-MAX	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification:		Environment Class:	EURO 5
Customer company :	MARINE HARVEST PIETERS NV	Co2:	112g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	C-MAX Trend St/St 115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes			
Variant car:		Engine size:	1560			
Gear box :	Manueel	Number of places:	5			
Number of gears:	6	Number of doors:	5			
нр:	116	kW:	85			
Fisc HP		Imported vehicle:				
Animals transported:		Smoked in vehicle:	No			
Due date vehicle inspection:		Extra set of tires:	No			
		Use:	Unknown			
General condition:						



www.vabfleetservices.be Date: 25/10/2017 2/4

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:		Cert. of conformity:	OK
Cert. of reg. copy / Part 2:	OK	Insurance certificate :	
Warning vest:	OK	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :	OK	Car radio :	ОК
Mobile phone kit :		Extinguisher :	OK
		Warning triangle :	ОК
First aid kit :	OK	Oil level :	
Jack, wheelspanner :	OK	Filled up :	0

### Wheels and tyres: Summer tires

Wheel FL:	CONTINENTAL	Tyre:	OK [x	] 4-6/	Rim:	/ Hubcap:
Wheel RL:	MICHELIN	Tyre:	OK [x	] 4-6/	Rim:	/ Hubcap:
Wheel FR:	CONTINENTAL	<b>Tyre:</b> [x]	OK [x	] 4-6/	Rim:	/ Hubcap:
Wheel RR:	MICHELIN	Tyre:	OK [x	] 4-6/	Rim:	/ Hubcap:
Wheel RES:	ANDERE	Tyre:	OK	/	Rim:	/ Hubcap:

	Width	Height	Туре	Rim	Index
Front tyre	215	55	R	16	Н
Rear tyre	215	55	R	16	Н

Remark:

### Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 25/10/2017 3/4

#### Conclusion

### Bodywork \& windows

[x] FRONT DOOR/LEFT/CENTER OTHER DAMAGES SLECHTE HERSTELING + DEUK

[x] BONNET/CENTER/RIGHT/FRONT CHIPS

[x] FRONT BUMPER/LEFT CHIPS

[x] FRONT BUMPER/RIGHT CHIPS

### STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[X] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

[x] REAR MUDGUARD/RIGHT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)

[x] FRONT DOOR/LEFT/REAR SCRATCH WITH PAINT DAMAGE

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
0	0	0		0
HOG: 0	BG: 0		NA Deprec.	0
			0.00%	
			TOTAL	



www.vabfleetservices.be Date: 25/10/2017 4/4

[x] = Status Modification

Pictures: No

**CIRCUMSTANCES** 

#### NORMAL CONCLUSION

				NORWAL CONCLUSION			
Extra Time :	0 min	Waiting t	ime: 0 mir	1	Towing time :	0 min	
		Reason:			Reason:		
NOT EXECUTED	: No	•			•		
Reason:							
Remark:							
Prices in EUR	without VAT						
Authorized by				Executed by VAB Fleet Se	ervices		
customer :				Executed by VIID Fleet Bo	51 (1005)		
Remark authorized	l customer :						
Date :	25/10/2017	Hour :	12:58				
Company :							
Executed by VAB I Services	Fleet						
E-Mail :	@						
Signature authorized	l by customer						
			_				