

www.vabfleetservices.be Date: 09/05/2017 1/5

B379X0

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner:		Mileage :	65575 KM
File nr. :	1395408	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1CNA786 / TMBHT21Z	AC2109718 /	yr of constructionr :	2012 / 00
E-File nr. :		First registration :	09/01/2012
VFS-nr. :		Color :	BLACK
Make + Model :	SKODA / OCTAVIA COMBI	Fuel type :	DIESEL
Object nr. :	5001	Fuel:	
Classification :		Environment Class:	EURO 5
Customer company :	INBEV BELGIUM SA	Co2:	123g/km
Driver :		Remote controls:	2
Covering:	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan):	0
Vehicle type :	OCTAVIA COMBI Ambiente DPF DSG 105PK Aut	Country registration :	BELGIUM

Variant car:	BREAK	Engine size:	1598
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
нр:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Metallic paint:

Yes



www.vabfleetservices.be Date: 09/05/2017 2/5

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :			Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Winter tires

Wheel FL:	[x]	MICH	ELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	/	Hubcap :	
Wheel RL:	[x]	BRIDO	GESTONE	Tyre:		OK	[x]	4-6 /	Rim:	[x]	/	Hubcap:	
Wheel FR:	[x]	MICH	ELIN	Tyre:	[x]	OK	[x]	2-4 /	Rim:		/	Hubcap : [x]	SCRATCHED
Wheel RR:	[x]	BRIDO	GESTONE	Tyre:		OK	[x]	4-6 /	Rim:		/	Hubcap: [x]	SCRATCHED
Wheel RES:	[x]	MICH	ELIN	Tyre:		OK	[x]	>6 /	Rim:		/	Hubcap:	
		[x]	Wi	idth			He	eight		Туре		Rim	Index
Fron	t tyre		10	95			-	65		R		15	M+S

 [x]	Width	Height	Туре	Rim	Index
Front tyre	195	65	R	15	M+S
Rear tyre	195	65	R	15	M+S

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap :
1					

_	[x]	Width	Height	Туре	Rim	Index
	Front tyre	0	0	R	0	
	Rear tyre	0	0	R	0	

Remark:



Pieces

Number Code

WHEEL CAP

APPRAISAL

09/05/2017 Date: www.vabfleetservices.be 3/5

_					
Во	dywork \& windows				
[x]	REAR DOOR/CENTER/RIGHT		SCRATCH WITH PAINT DAMAGE		
[x]	REAR MUDGUARD/LEFT/FRONT		SCRATCH WITH PAINT DAMAGE		
[x]	REAR WINDOW STYLE/CENTER/LEFT/UI	P	SCRATCH (WITHOUT PAINT DAMAGE) POLLIEREN	
[x]	ROOF/REAR/LEFT		SCRATCH (WITHOUT PAINT DAMAGE) POLLIEREN	
[x]	REAR DOOR/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE		
[x]	BONNET/CENTER/LEFT		SCRATCH (WITHOUT PAINT DAMAGE		
[x]	FRONT BUMPER/RIGHT		CHIPS		
ST	ATUS: NOT ACCEPTAB	LE			
B۸	dance with 10 and a dance				
<u> </u>	dywork \& windows				
	WINDSCREEN/CENTER/RIGHT		WINDOW DAMAGE		
		Description	WINDOW DAMAGE Unit price	Depr.	Total
	WINDSCREEN/CENTER/RIGHT	Description WINDOW REPAIR		Depr.	
[x]	WINDSCREEN/CENTER/RIGHT Number Code		Unit price	Depr.	Total 58.80 EUR
[x]	WINDSCREEN/CENTER/RIGHT Number Code 2 I 1 i-vab-herstr-01		Unit price 58.80 EUR	Depr.	
[x]	WINDSCREEN/CENTER/RIGHT Number Code 2 I 1 i-vab-herstr-01	WINDOW REPAIR	Unit price 58.80 EUR SCRATCH WITH PAINT DAMAGE	-	58.80 EUR
[x]	WINDSCREEN/CENTER/RIGHT Number Code 2 I 1 i-vab-herstr-01 FRONT MUDGUARD/RIGHT/CENTER	WINDOW REPAIR Repair paint - LI	Unit price 58.80 EUR SCRATCH WITH PAINT DAMAGE	Depr.	58.80 EUR Total
[x]	WINDSCREEN/CENTER/RIGHT Number Code 2 I 1 i-vab-herstr-01 FRONT MUDGUARD/RIGHT/CENTER 4 0 LU =0.00 EUR	WINDOW REPAIR Repair paint - LI	Unit price 58.80 EUR SCRATCH WITH PAINT DAMAGE	Depr.	58.80 EUR Total
[x]	WINDSCREEN/CENTER/RIGHT Number Code 2 I 1 i-vab-herstr-01 FRONT MUDGUARD/RIGHT/CENTER 4 0 LU =0.00 EUR Cessories and others	WINDOW REPAIR Repair paint - LI	Unit price 58.80 EUR SCRATCH WITH PAINT DAMAGE New paint - E	Depr.	58.80 EUR Total
[x]	WINDSCREEN/CENTER/RIGHT Number Code 2 I 1 i-vab-herstr-01 FRONT MUDGUARD/RIGHT/CENTER 4 0 LU =0.00 EUR Cessories and others OUTSIDE MIRROR RIGHTHAND SIDE	WINDOW REPAIR Repair paint - LI 220.18 EUR	SCRATCH WITH PAINT DAMAGE New paint - E SCRATCH WITH PAINT DAMAGE	Depr. 50 %	58.80 EUR Total 220.18 EUI
[x] Ac	WINDSCREEN/CENTER/RIGHT Number Code 2 I 1 i-vab-herstr-01 FRONT MUDGUARD/RIGHT/CENTER 4 0 LU =0.00 EUR Cessories and others OUTSIDE MIRROR RIGHTHAND SIDE Number Code	WINDOW REPAIR Repair paint - LI 220.18 EUR Description	Unit price 58.80 EUR SCRATCH WITH PAINT DAMAGE New paint - E SCRATCH WITH PAINT DAMAGE Unit price	Depr. 50 %	58.80 EUR Total 220.18 EUI
[x] Acc [x]	WINDSCREEN/CENTER/RIGHT Number Code 2 I 1 i-vab-herstr-01 FRONT MUDGUARD/RIGHT/CENTER 4 0 LU =0.00 EUR Cessories and others OUTSIDE MIRROR RIGHTHAND SIDE Number Code 3 I 1 i-vab-sp-01	WINDOW REPAIR Repair paint - LI 220.18 EUR Description	Unit price 58.80 EUR SCRATCH WITH PAINT DAMAGE New paint - E SCRATCH WITH PAINT DAMAGE Unit price	Depr. 50 %	58.80 EUR Total 220.18 EUI

Unit price

30.00 EUR

Depr.

50 %

Total

30.00 EUR

Description



www.vabfleetservices.be Date: 09/05/2017 4/5

1	2	3	4	5	6	7	8	9	10
30.00	58.80	115.56	220.18	0	0	0	0	0	0
15.00	58.80	115.56	110.09	0	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
424.54		0	250.18	174.36
299.45	NA Deprec.		BG: 0	HOG: 0
	0.00%			
299.45	TOTAL			



09/05/2017 Date: www.vabfleetservices.be 5/5

[x] = Status Modification

Pictures: No							
CIRCUMS	TANCES			NORMAL CONCLU	SION		
Extra Time :	0 min	Waiting time : Reason :	0 min		Towing time : Reason :	0 min	
NOT EXECUTED : Reason :	No	_					
Remark :							
Prices in EUR w	rithout VAT						
Authorized by customer :				Executed by VAB Fleet Se	rvices		
Remark authorized	customer :						
Date : Company :	09/05/2017	Hour: 09:	54				
Executed by VAB Fl Services	leet						
E-Mail:	@						
Signature authorized l	by customer						