

www.vabfleetservices.be Date: 06/11/2017 1/4

D6U2FP

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	95818 KM
File nr. :	1454244	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EDW364 / WVWZZZ1KZDV	W103833 /	yr of constructionr :	/
E-File nr. :		First registration :	01/11/2012
VFS-nr. :		Color :	BLACK
Make + Model :	VOLKSWAGEN / GOLF	Fuel type :	DIESEL
Object nr. :	67285	Fuel :	
Classification:		Environment Class:	EURO 5
Customer company :	EMTEX BVBA	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	GOLF BER BlueMotion DPF 105PK	Country registration :	BELGIUM

Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Metallic paint:

Yes



www.vabfleetservices.be Date: 06/11/2017 2/4

Original registr. number : OK Service manual : OK [x] Cert. of conformity: Cert. of reg. / Part 1: OK Insurance certificate: Cert. of reg. copy / Part 2: OK [x]Warning vest: Transport licence: Tax certificate: Navigation CD/SD/DVD Fuel card : Car radio: OK [x] Extinguisher: Mobile phone kit : OK [x] Warning triangle: OK [x] OK Oil level: OK First aid kit : [x] [x] Filled up: 0 Jack, wheelspanner :

Wheels and tyres: Winter tires

						0			J.F			
		[x]	Width		Hei	ight			Туре		Rim	Index
Wheel RES:	[x]		Tyre :	OK		/	Rim:				/ Hubcap:	
			•								-	
Wheel RR:	[x]	PIRELLI	Tyre:	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel FR:	[x]	FULDA	Tyre: [x]	OK	[x]	2-4 /	Rim:				/ Hubcap:	
Wheel RL:	[x]	PIRELLI	Tyre:	OK	[x]	2-4 /	Rim:				/ Hubcap:	
Wheel FL:	[x]	FULDA	Tyre:	OK	[x]	2-4 /	Rim:				/ Hubcap:	

[x] Width		Height	Type	Rim	Index	
Front tyre	195	65	R	15	M+S	
Rear tyre	195	65	R	15	M+S	

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:
i					

_	[x]	Width	Height	Туре	Rim	Index
	Front tyre	0	0	R	0	
	Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 06/11/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Во	dywork	\& window	'S								
[x]		JMPER/CENTER/				SCRATCH WITH PAINT DAMAGE					
[x]	REAR BU	JMPER/CENTER/	RIGHT			SCRATCH (WITH	OUT PAINT DA	MAGE)			
[x]	REAR MU	JDGUARD/LEFT	/CENTER			DENT					
[x]	REAR MU	JDGUARD/LEFT	/FRONT			SCRATCH WITH	PAINT DAMAG	Έ			
ST	ATUS:	NOT AC	CEPTAB	LE							
Inte	erior										
[x]	DOOR IN	REAR L				CUT / TORN					
				Repair pair	nt - LI	New paint - E		Depr		Total	
	1 5 LU =24.	00 EUR		0 EUR				50 %		24.00 EUR	
Oth	ners										
	RIM REA	R RIGHT									
	Number	Code		Description	ı		Unit pr	rice Depr		Total	
	2 I 1	i-vab-herstalu-02		REPAIR AI	LOY WHEEL	EL 95.00 EUR 95.00 EUR					
Pie	ces										
	Number	Code		Description	l		Unit pr	rice Depr		Total	
	1 1	UPHOLSTERY I	DOOR				90.00 E	UR 50 %		90.00 EUR	
	1	2	3	4	5	6	7	8	9	10	
	114.00	95.00	0	0	0	0	0	0	0	0	
	57.00	95.00	0	0	0	0	0	0	0	0	
	INNOV	ATIVE	TRAD	ITIONAL	1	GENERAL					
	95.	.00	11	14.00		0	0 20				
	НО	G: 0	В	G: 0			NA Dep	orec.		152.00	
_											

0.00% TOTAL

152.00



www.vabfleetservices.be Date: 06/11/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUM	STANCES		NORMAL CONCLUSION					
Extra Time :	0 min	Waiting time: 0 mi Reason:	n	Towing time : Reason :	0 min			
NOT EXECUTE Reason:	D: No							
Remark :								
Prices in EUF	R without VAT							
Authorized by customer :			Executed by VAB	Fleet Services				
Remark authoriz	zed customer :							
Date : Company :	06/11/2017	Hour: 15:12						
Executed by VAI Services	B Fleet							
E-Mail :	@							
Signature authoriz	zed by customer							