

D7KJ59

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	156300 KM
File nr. :	1454836	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EDG087 / W0LGT5EJ3D1021072 /		yr of constructionr :	/
E-File nr. :		First registration :	26/10/2012
VFS-nr. :		Color :	GREY
Make + Model :	OPEL / INSIGNIA	Fuel type :	DIESEL
Object nr. :	77590	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	LOGIS VZW	Co2:	114g/km
Driver :		Remote controls:	2
Covering :	PARTIAL LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	INSIGNIA BER ecofl.Cosmo S/S DPF 110PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	1956
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	4
HP:	110	kW:	81
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK			Service manual :	OK	[x]
Cert. of reg. / Part 1:				Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]		Insurance certificate :		
Warning vest :	OK	[x]		Transport licence :		
Tax certificate :				Navigation CD/SD/DVD	OK	[x]
Fuel card :				Car radio :	OK	[x]
Mobile phone kit :				Extinguisher :	OK	[x]
				Warning triangle :	OK	[x]
First aid kit :	OK	[x]		Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x] 2-4 /	Rim :	/ Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x] 2-4 /	Rim :	/ Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x] OK	[x] 2-4 /	Rim :	/ Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x] 2-4 /	Rim :	/ Hubcap :
Wheel RES:	[x]		Tyre :	OK	/	Rim :	/ Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	17	W
Rear tyre	225	55	R	17	W

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

[x] REAR BUMPER/RIGHT/RIGHT DENT

Interior

[x] SEAT FL CARVED

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] FRONT BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Accessories and others

[x] DOORHANDLE MISSING/INCOMPLETE

	Repair paint - LI	New paint - E	Depr.	Total
2 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	CHROOMSTRIP	15.00 EUR	50 %	15.00 EUR

1	2	3	4	5	6	7	8	9	10
211.80	39.00	0	0	0	0	0	0	0	0
105.90	19.50	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	250.80	0	250.80
HOG: 0	BG: 0		NA Deprec. 125.40
			0.00%
			TOTAL 125.40

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/11/2017 Hour : 11:19 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	