

www.vabfleetservices.be Date: 15/11/2017 1/4

DDB47F

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 58380 KM File nr. : Mileage start / arrival: 0 / 01459388 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1FVM413 / WVWZZZAUZEW163598 / E-File nr. : First registration: 07/11/2013 Color: VFS-nr.: **BROWN** Make + Model : Fuel type : VOLKSWAGEN / GOLF **DIESEL** Object nr. : Fuel: 11380 Classification: **Environment Class:** EURO 5 Customer company: Co2: **IMEC VZW** 99g/kmDriver : Remote controls: TISSUE Covering: Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): 0 Vehicle type: GOLF BER Trendline 105PK Country registration: **BELGIUM**

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
нр:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:		1	



www.vabfleetservices.be Date: 15/11/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest:	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

		[x] W	'idth			Н	eight		Type		Rim	Index
Wheel RES:	[x]		Tyre:		OK		/	Rim:		/	Hubcap:	
Wheel RR:	[x]	CONTINENTAL	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel FR:	[x]	CONTINENTAL	Tyre:	[x]	OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel RL:	[x]	CONTINENTAL	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel FL:	[x]	CONTINENTAL	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	V
Rear tyre	195	65	R	15	V

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:
i					

_	[x]	Width	Height	Туре	Rim	Index
	Front tyre	0	0	R	0	
	Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 15/11/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT

SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] BONNET/CENTER/RIGHT OTHER DAMAGES CHEMISCHE INWERKING

 Repair paint - LI
 New paint - E
 Depr.
 Total

 1 0 LU = 0.00 EUR
 290.08 EUR
 50 %
 290.08 EUR

1	2	3	4	5	6	7	8	9	10
290.08	0	0	0	0	0	0	0	0	0
145.04	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
0	290.08	0		290.08
HOG: 0	BG: 0		NA Deprec.	145.04
			0.00%	,
			TOTAL	145.04



www.vabfleetservices.be Date: 15/11/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMS	TANCES		UNDER CONDITION - VEHICLE WET				
Extra Time :	0 min	Waiting time: 0 m Reason:	in	Towing time : Reason :	0 min		
NOT EXECUTED : Reason :	No	I		I			
Remark :	1						
Prices in EUR v	vithout VAT						
Authorized by customer :			Executed by VAE	3 Fleet Services			
Remark authorized	customer :						
Date : Company :	15/11/2017	Hour: 14:19					
Executed by VAB F Services	leet						
E-Mail :	@						
Signature authorized	by customer		1				