



VOLVO V40: 1EHK788			
Vinnnumber:	YV1MV8481D2017534	Versionname:	V40 D2 Base 115PK
First Registrationdate:	4/12/2012	Fiscalpower:	
Expertise Mileage:	104213	Power Kw:	84
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3433
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Central consol F
GPS storage	HD Luggage cover
GPS storage	Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control


Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
Winter tyres:	205/55/16/91 H LightMetal			
	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			783,88
Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)			283,80



Alloy rim R L, Scratch(es), Acceptable	0,00
No pictures to display	

Wing R R, Bump(s), Acceptable	0,00
No pictures to display	
Alloy rim R R, Scratch(es), Acceptable	0,00
No pictures to display	
Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)	290,08
	
Door R R, Bump(s) and scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
	
Boot carpet, Missing, E - Replace	20,00
	
Wing R L, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper R, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper grille, Damaged, Acceptable	0,00
	
Door F R, Bad repair, Acceptable	0,00



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Floor covering F L, Damaged, Acceptable	0,00
---	------



Seat cover F L, Deformed, Acceptable	0,00
--------------------------------------	------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

