



VOLVO S60: 1EHW148			
Vinnnumber:	YV1FS84A1D2207629	Versionname:	S60 BER D2 Kinetic St/St
First Registrationdate:	7/12/2012	Fiscalpower:	115PK
Expertise Mileage:	140279	Power Kw:	84
Bodytype:	Berline	Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes		
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Central consol F
GPS storage	Front parking sensors
GPS storage	HD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
Winter tyres:	235/45/17/97 H LightMetal			
	Fr.L.	Pirelli: 3 mm	Fr.R.	Pirelli: 3 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			0,00
Floor covering F L, Burned, Smart repair			64,32



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Ignition key, Missing, E - Replace 150,00



Bumper R, Bump(s) and scratch(es), Smart repair 110,64



Door panel R R, Scratch(es), Smart repair 110,64



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 220,18



Seat cover R L, Stain, Cleaning 15,00



Seat cover R L, Burned, Smart repair 64,32



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Bumper grille, Damaged, E - Replace 32,40



Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete) 310,50



Wing R R, Bump(s), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Bump(s), Acceptable 0,00

No pictures to display

Door seal F R, Tear, E - Replace 54,00



Door panel F R, Damaged, Smart repair 110,64



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Backrest cover F L, Crack, P - Check 0,00



Door F R, Bump(s) and scratch(es), Le - Replace and paint

0,00

