


MERCEDES CLA: 1GJA069

Vinnnumber:	WDD1173011N076078	Versionname:	CLA BER 200 CDI 136PK
First Registrationdate:	20/02/2014	Fiscalpower:	
Expertise Mileage:	98734	Power Kw:	100
Bodytype:	Berline	Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4206
Battery functioning	Yes		
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Sun Roof electric
GPS storage	HD	Panoramic roof
GPS storage		Central consol F
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-artificial leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/45/17/94 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Vredestein: 6 mm	Re.R.	Vredestein: 6 mm



Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1057,35
Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Windscreen, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Scratch(es), Acceptable	0,00

No pictures to display		
Wing R L, Scratch(es), LI - Repair and paint (complete)		308,20
		
Door F R, Scratch(es), Acceptable		0,00
No pictures to display		
Rearview mirror R complete, Scratch(es), Acceptable		0,00
No pictures to display		
Seat cover F L, Tear, Acceptable		0,00
		
Front bumper, Stone chip(s), Acceptable		0,00
No pictures to display		
Engine protective plate, Tear, E - Replace		74,00
		
Interior, Stain, Cleaning		50,00
		
		
Door R L, Scratch(es), LI - Repair and paint (complete)		318,35
		
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)		95,00
		
		