



PEUGEOT 3008: 1EJR649				
Vinnnumber:	VF30U9HD8CS247567	Versionname:	3008 e-HDi Allure STT FAP BMP 115PK Aut.	
First Registrationdate:	1/01/2013	Fiscalpower:		
Expertise Mileage:	144690	Power Kw:	84	
Bodytype:		Body color	Blue	
Gearbox:	Automatic	Paint type	Metalic	
Transmission:	Front	Rims summer	Aluminium	
Fueltype:	Diesel	Oil level	OK	
Battery functioning	Yes	Parking lot	4613	
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	No			
Options				
Radio CD		Panoramic roof		
GPS storage	HD	Central consol F		
GPS storage		Luggage cover		
Windows electric F		Front parking sensors		
Windows electric R		Rear parking sensors		
Cruise Control		Type of Tow bar	Tow bar removable	
Steering wheel multifunctional				
Seats F heated				
Radio multimedia				
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining leather			
Type of climate control	Autom climate control			
Head-up Display				
Limited Technical Inspection				
Power steering	Yes	Battery functioning	Yes	
Airco functioning	OK	Sound engine	OK	
Tires wear profile	OK	Clutch test	OK	
Idle position	OK	Wiper fluid level	OK	
Engine startingtime	OK	Lighting	OK	
Exhaust gass	OK	Wiperblades	OK	
Transmission	OK			
Handbrake	OK			
Degree of wear				
	225/50/17/96 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm
Assistance equipment				
Spare tyre compact	Yes	Jack	Yes	
Total cost ex VAT		0,00		
Bumper corner R R, Scratch(es), Acceptable		0,00		
<i>No pictures to display</i>				
Wing R R, Bump(s), LI - Repair and paint (complete)		0,00		
				
Front bumper, Scratch(es), Smart repair		0,00		



Door seal F L, Damaged, E - Replace

0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

0,00



Trunk lid covering R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

0,00



Bumper corner R L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

0,00



Bonnet, Chemical polution, LI - Repair and paint (complete)

0,00



Wing R L, Bump(s), PDR - Knock out without painting

0,00



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Bump(s), Acceptable

0,00

No pictures to display