



CITROEN C4 Picasso: 1EDI066			
Vinnnumber:	VF7UARHB8CJ727668	Versionname:	GR.C4 PICASSO
First Registrationdate:	26/10/2012		7pl.Excl.FAP BMP 150PK
Expertise Mileage:	106400	Fiscalpower:	Aut
Bodytype:	MPV	Power Kw:	110
Gearbox:	Automatic	Body color	Brown
Transmission:	Front	Paint type	Metalic
Fueltype:	Diesel	Rims summer	Aluminium
Battery functioning	Yes	Oil level	OK
Number of doors	5	Parking lot	3413
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options			
Radio CD		Panoramic roof	
GPS storage		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar fixed
Steering wheel multifunction			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		
Level control			

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
Winter tyres:	215/55/16/93 H LightMetal			
	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment			
Repair kit	No	Compressor	No
Total cost ex VAT			3395,62
Door R R, Chemical polution, LI - Repair and paint (complete)			318,35



Rear window, Scratch(es), E - Replace	370,00
---------------------------------------	--------



Wing R L, Scratch(es), Acceptable	0,00
No pictures to display	
Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08



Door panel R L, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F L, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper corner R L, Scratch(es), Acceptable	0,00
No pictures to display	
Tailgate, Scratch(es), Acceptable	0,00
No pictures to display	
Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80



Wing F L, Scratch(es), Acceptable	0,00
No pictures to display	
Door F L, Accident, Le - Replace and paint	1082,52



Interior, Dirty, Cleaning	75,00
---------------------------	-------



Tyre repair kit, Missing, E - Replace	210,53
No pictures to display	
Wing R R, Scratch(es), Acceptable	0,00
No pictures to display	

Door F R, Scratch(es), Acceptable	0,00
No pictures to display	
Trunk lid covering R, Scratch(es), Smart repair	110,64
	
Door R L, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	
Door trim R R, Scratch(es), Acceptable	0,00
No pictures to display	
Sill outer L, Accident, LI - Repair and paint (complete)	310,50
	
Wing F R, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
	
Bumper moulding R L, Broken, E - Replace	14,40
	
Bumper corner R R, Scratch(es), Acceptable	0,00
No pictures to display	