



BMW 1 HATCH: 1LEH877

Vinnumber:	WBA1V910005B19226	Versionname:	1.5 116D
First Registrationdate:	4/09/2015		EFFICIENTDYNAMICS
Expertise Mileage:	62192		EDIT. (85KW)
Bodytype:	Hatchback	Fiscalpower:	
Gearbox:	MAN 6 VIT	Power Kw:	85
Transmission:		Body color	Black
Fueltype:	Diesel	Paint type	Metalic
Battery functioning	Yes	Rims summer	Aluminium
Number of doors	5	Oil level	OK
Number of seats	5	Parking lot	1314
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

Winter tyres:	205/55/16/91 H LightMetal			
	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1247,70
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)			95,00



Bonnet, Increased paint layer, No repair	0,00
--	-------------

No pictures to display	
Front bumper, Scratch(es), Acceptable	0,00
No pictures to display	
Wing R R, Chemical polution, LI - Repair and paint (complete)	308,20
 	
Tailgate, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
  	
	
Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Door panel R R, Scratch(es), Acceptable	0,00
 	
Mirror side blinker R, Broken, E - Replace	59,00
 	
Door panel F R, Scratch(es), E - Replace	114,00
 	
Seat cover F L, Worn, Acceptable	0,00
  	
Windscreen, Stone chip(s), Acceptable	0,00
No pictures to display	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
  	
	
Roof, Chemical polution, LI - Repair and paint (complete)	481,50

