



VOLVO V70: 1EPG417			
Vinnnumber:	YV18W31A1D1270065	Versionname:	V70 D3 Kinetic St/St 136PK
First Registrationdate:	13/02/2013	Fiscalpower:	
Expertise Mileage:	180926	Power Kw:	100
Bodytype:	Break	Body color	Dark Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2105
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
	225/55/16/99 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1628,59
Bonnet, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Wing R R, Scratch(es), LI - Repair and paint (complete)			0,00



Dashboard, Damaged, Smart repair			110,64
----------------------------------	--	--	---------------

Dashboard, Damaged, Smart repair			110,00
			
Bonnet, No damage, Acceptable			0,00
			
Interior, Dirty, Cleaning			100,00
			
			
			
			
Door R L, Scratch(es), Acceptable			0,00
No pictures to display			
Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)			254,16
			
			
Wing R L, Scratch(es), Acceptable			0,00
No pictures to display			
Rearview mirror R complete, Damaged, Le - Replace and paint			307,00
			
			
Door F R, Scratch(es), It - Spot repair			115,56



Tailgate, No damage, Acceptable	0,00
---------------------------------	------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Door R R, Scratch(es), LI - Repair and paint (complete)	382,02
---	--------



Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	264,21
---	--------

