



|                         |                   |              |                    |
|-------------------------|-------------------|--------------|--------------------|
| MERCEDES B: 1ESH195     |                   |              |                    |
| Vinnnumber:             | WDD2462001J152296 | Versionname: | B 180 CDI BE 109PK |
| First Registrationdate: | 7/03/2013         | Fiscalpower: |                    |
| Expertise Mileage:      | 103909            | Power Kw:    | 80                 |
| Bodytype:               | Hatchback         | Body color   | Black              |
| Gearbox:                | MAN 6 VIT         | Paint type   | Metalic            |
| Transmission:           | Front             | Rims summer  | Steel              |
| Fueltype:               | Diesel            | Oil level    | OK                 |
| Battery functioning     | Yes               | Parking lot  | 3212               |
| Number of doors         | 5                 |              |                    |
| Number of seats         | 5                 |              |                    |
| Number head rests       | 5                 |              |                    |
| Rims summer             | Steel             |              |                    |
| Category                | Passenger Car     |              |                    |
| Oil level               | OK                |              |                    |

|                                |                        |
|--------------------------------|------------------------|
| Options                        |                        |
| Radio CD                       | Central consol F       |
| GPS storage                    | HD Luggage cover       |
| GPS storage                    |                        |
| Windows electric F             |                        |
| Windows electric R             |                        |
| Steering wheel multifunctional |                        |
| Type of headlighting           | Headlighting Halogen   |
| Type of GPS                    | GPS big screen color   |
| Type of Lining                 | Lining leather         |
| Type of climate control        | Manual climate control |

|                              |    |                     |     |
|------------------------------|----|---------------------|-----|
| Limited Technical Inspection |    |                     |     |
| Airco functioning            | OK | Battery functioning | Yes |
| Tires wear profile           | OK | Power steering      | Yes |
| Idle position                | OK | Sound engine        | OK  |
| Engine startingtime          | OK | Clutch test         | OK  |
| Exhaust gass                 | OK | Wiper fluid level   | OK  |
| Handbrake                    | OK | Transmission        | OK  |
|                              |    | Lighting            | OK  |
|                              |    | Wiperblades         | OK  |

|                |                      |                |       |                |
|----------------|----------------------|----------------|-------|----------------|
| Degree of wear |                      |                |       |                |
| Winter tyres:  | 195/65/15/91 T Steel |                |       |                |
|                | Fr.L.                | Uniroyal: 5 mm | Fr.R. | Uniroyal: 5 mm |
|                | Re.L.                | Pirelli: 5 mm  | Re.R. | Pirelli: 5 mm  |

|                                                           |     |            |         |
|-----------------------------------------------------------|-----|------------|---------|
| Assistance equipment                                      |     |            |         |
| Repair kit                                                | Yes | Compressor | Yes     |
| Total cost ex VAT                                         |     |            | 1158,94 |
| Roof, Chemical polution, LI - Repair and paint (complete) |     |            | 481,50  |



|                                           |       |
|-------------------------------------------|-------|
| Wheel cover R R, Scratch(es), E - Replace | 30,00 |
|-------------------------------------------|-------|





|                               |      |
|-------------------------------|------|
| Door R L, Bump(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display

|                                          |      |
|------------------------------------------|------|
| Glove box cover, Scratch(es), Acceptable | 0,00 |
|------------------------------------------|------|

No pictures to display

|                                                             |        |
|-------------------------------------------------------------|--------|
| Front bumper, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|-------------------------------------------------------------|--------|



|                                                                          |        |
|--------------------------------------------------------------------------|--------|
| Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) | 115,56 |
|--------------------------------------------------------------------------|--------|



|                               |      |
|-------------------------------|------|
| Armrest R M, Worn, Acceptable | 0,00 |
|-------------------------------|------|



|                                   |      |
|-----------------------------------|------|
| Door R R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|                                   |      |
|-----------------------------------|------|
| Tailgate, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|                                                             |        |
|-------------------------------------------------------------|--------|
| Bonnet, Chemical polution, LI - Repair and paint (complete) | 290,08 |
|-------------------------------------------------------------|--------|



|                                   |      |
|-----------------------------------|------|
| Door F R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|                               |      |
|-------------------------------|------|
| Wing R R, Bump(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display

|                                   |      |
|-----------------------------------|------|
| Door F L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|                                   |      |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|                                        |      |
|----------------------------------------|------|
| GPS, Not functioning (well), P - Check | 0,00 |
|----------------------------------------|------|



|                                           |       |
|-------------------------------------------|-------|
| Wheel cover F R, Scratch(es), E - Replace | 30,00 |
|-------------------------------------------|-------|

