


MERCEDES A: 1GFZ904

Vinnnumber:	WDD1760121J233109	Versionname:	A 180 CDI BE 109PK
First Registrationdate:	29/01/2014	Fiscalpower:	
Expertise Mileage:	122777	Power Kw:	80
Bodytype:	Hatchback	Body color	Purple
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1225
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining semi-leather
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------


Total cost ex VAT	1009,20
Dashboard, Damaged, Smart repair	110,64



Bumper R, Bump(s), LI - Repair and paint (complete)	211,80
---	---------------



Roof pillar L, Bad repair, Paint	0,00
----------------------------------	-------------



Door R L, Bad repair, Paint	0,00
-----------------------------	------



Wing R R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Bonnet, Scratch(es), LI - Repair and paint (complete)	290,08
---	--------



Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display


Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Door F L, Stone chip(s), Acceptable	0,00
-------------------------------------	------

No pictures to display

Wing R L, Bad repair, Paint	0,00
-----------------------------	------



Tailgate, Bump(s), LI - Repair and paint (complete)	301,68
---	--------

