



VOLVO V70: 1FHM641			
Vinnnumber:	YV1BW88A1E1286248	Versionname:	V70 D4 Kinetic 163PK
First Registrationdate:	1/07/2013	Fiscalpower:	
Expertise Mileage:	155576	Power Kw:	120
Bodytype:	Break	Body color	Dark Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1604
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		


Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunction	Tow bar removable
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Winter tyres:	225/50/17/98 H LightMetal			
	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment	
Repair kit	Yes
Compressor	Yes
Total cost ex VAT	1621,80
Door R L, Scratch(es), Acceptable	0,00
No pictures to display	
Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Rear window, Scratch(es), E - Replace	420,00






Alloy rim F R, Rust, Acceptable 0,00



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L, Rust, Acceptable 0,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 369,84



Roof, Scratch(es), LI - Repair and paint (complete) 577,80



Rocker panel inner R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Rust, Acceptable 0,00



Moulding windscreen U, Scratch(es), Acceptable 0,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,16

