




VOLVO V40: 1E00198			
Vinnnumber:	YV1MV8481D2038924	Versionname:	V40 D2 Base 115PK
First Registrationdate:	7/02/2013	Fiscalpower:	
Expertise Mileage:	118949	Power Kw:	84
Bodytype:		Body color	Light Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3821
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Cruise Control	
Steering wheel multifunction	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	205/55/16/91 V LightMetal			
	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			2150,74
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)			95,00




Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Seat cover F L, Hole, E - Replace 360,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Interior, Dirty, Cleaning 100,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80






Rocker panel inner F L, Scratch(es), LI - Repair and paint (complete)	115,56
---	--------



Bonnet, Chemical pollution, LI - Repair and paint (complete)	290,08
--	--------



Roof, Chemical pollution, LI - Repair and paint (complete)	481,50
--	--------

